


STANDARD INSTRUMENT DEPARTURES (SID)
DEPARTURES - RWYS SOUTH
TINDAL, NT (YPTN)

27 NOV 2025

ATIS 112.3 124.0 316.3	TWR 119.7 257.3	APP 120.95 261.4	SMC 135.85 264.3	FIA (AH) BN CEN 122.6	CTAF+AFRU (AH) AFIS 119.7	Bearings are Magnetic Elevations in FEET AMSL
---------------------------	--------------------	---------------------	---------------------	--------------------------	---------------------------------	--



DAPMA TWO DEPARTURE
MIGAX THREE DEPARTURE
MILIV FOUR DEPARTURE
DOSAM FOUR DEPARTURE
GREGA FOUR DEPARTURE

RWY 14

- Track 136°
- AT 1000ft BUT NOT BEFORE DER

For DAPMA

- Turn LEFT, track 061°
- Intercept cleared route

For MIGAX

- Turn LEFT, track 124° to MIGAX, then as cleared

For MILIV

- Turn RIGHT, track 140° to MILIV, then as cleared

For DOSAM & GREGA

- Turn RIGHT, track 191°
- Intercept cleared route

RWY 32

- Track 316°
- AT 1000ft BUT NOT BEFORE DER

For DAPMA

- Turn RIGHT, track 136°
- Intercept cleared route

For MIGAX & MILIV

- Turn RIGHT, track 136°
- After crossing TN R-051° turn RIGHT
- Track 181°
- Intercept cleared route

For DOSAM & GREGA

- Turn LEFT, track 136°
- Intercept cleared route

COMMUNICATIONS FAILURE PROCEDURE

On recognition of Communications Failure:

- Squawk 7600
- Maintain last assigned vector for two minutes, and
- CLIMB IF NECESSARY TO MINIMUM SAFE ALTITUDE to maintain terrain clearance, then
- Proceed in accordance with the latest ATC route clearance acknowledged