

**AIP SUPPLEMENT  
(SUP)****H22/24****Effective: 202402200200 UTC**

AERONAUTICAL INFORMATION SERVICE,  
AIRSERVICES AUSTRALIA, GPO BOX 367,  
CANBERRA ACT 2601

For **DISTRIBUTION** queries, contact:  
Email: [aim.editorial@airservicesaustralia.com](mailto:aim.editorial@airservicesaustralia.com)

For **CONTENT** queries regarding this SUP, contact:  
Email: [pavel.davidyuk@perthairport.com.au](mailto:pavel.davidyuk@perthairport.com.au)

# **PERTH AIRPORT (YPPH) NEW TAXIWAY RESTRICTIONS FOR CODE C AND ABOVE AIRCRAFT**

## **1. INTRODUCTION**

- 1.1 This AIP SUP explains the restrictions for simultaneous operations of Code C and above aircraft on TWY H3 and the Terminal 4 Apron TWY in the Bay 12-13 area due to taxiway strip convergence overlap.
- 1.2 ERSA FAC YPPH TWY/TAXILANE INFRINGEMENTS point f. has been permanently amended by NOTAM with these restrictions.
- 1.3 A scope of works to realign the apron taxiway centreline, providing simultaneous Code C and below operations, is being investigated.

## 2. OPERATIONAL INFORMATION

- 2.1 The availability of simultaneous Code C and above aircraft operations for movements combinations outlined in the table below:

	ACFT to/from TWY H3 and TWY H4	ACFT to/from TWY H4 and TWY B
Code C Bay 12 pushback south onto APN TWY	Not AVBL	Code C and BLW - AVBL Code D and ABV – NOT AVBL
Bay 12 pushback north onto mouth of TWY B	Not AVBL	Not AVBL
Bay 12 pushback north onto T4 APN TWY	AVBL	AVBL
Bay 13 pushback south onto T4 APN TWY	AVBL	AVBL
Bay 13 pushback north onto T4 APN TWY	Not AVBL	AVBL
T3 APN TWY (behind Bays 12 and 13)	Not AVBL	AVBL

- 2.2 Where simultaneous movements are not AVBL, aircraft should expect to hold at the intermediate holding positions on TWY H3 (short of yellow cones) and TWY H4 (short of TWY B), as instructed by Perth ATC.
- 2.3 Refer to appendices for further information.

## 3. TECHNICAL QUESTIONS AND ADVICE

- 3.1 For additional information or clarification of information contained within this SUP please contact the airfield Safety & Operations Manager:

Darren McKenzie

Email: [Darren.McKenzie@perthairport.com.au](mailto:Darren.McKenzie@perthairport.com.au)

Phone: +61 8 9478 8441

## 4. CANCELLATION

- 4.1 This SUP will be cancelled when the permanent NOTAM C935/23 is incorporated into ERSA, expected 13 June 2024.


## 5. DISTRIBUTION

5.1 Airservices Australia website only.


### Appendices

1. Bay 12 Departures Tail into Mouth of TWY B.
2. Bay 13 & 14 Pushback Tail North
3. Bay 12 Departures Tail South
4. Bay 12 Pushback Code C ACFT Departures


1. Bay 12 Departures Tail into Mouth of TWY B



2. Bay 13 & 14 Pushback Tail North



3. Bay 12 Departures Tail South





4. Bay 12 Pushback Code C ACFT Departures

