

**MURWILLUMBAH****ELEV 18****FULL NOTAM SERVICE NOT AVBL**

NSW  
281952S 1532449E UTC +10 YMUR  
VAR 11 DEG E UNCR  
AD OPR Tweed Shire Council, PO Box 816, Murwillumbah, NSW, 2484. PH 02 6670  
2400. Website: www.tweed.nsw.gov.au.

**REMARKS**

1. AD Charges: All ACFT.
2. Pilot notes refer to Tweed Shire Council website.
3. Publicly accessible webcams AVBL.

**HANDLING SERVICES AND FACILITIES**

AVGAS AVBL (AH by appointment). PH 02 6672 4545.

**PHYSICAL CHARACTERISTICS**

01/19 34c Central 15M of first 500M S of RWY 19 DTHR WID 40 RWS 70  
grass/hard shale. Remainder grass. RWY LEN  
1,045M.

RWY 19 DTHR 245M.

**ATS AND AERODROME COMMUNICATION FACILITIES**

FIA BRISBANE CENTRE 119.5

**LOCAL TRAFFIC REGULATIONS**

1. TWY on NE side of RWY is not AVBL due to drains and trees.
2. In dry conditions, TWY on W and SE sides are AVBL.
3. When RWY wet, taxi on crown with care.
4. Due to industrial buildings at northern end of RWY, ACFT on approach for RWY 19 may not be visible. Please complete all checks in run-up bay provided.

**FLIGHT PROCEDURES**

1. Left hand circuits.
2. When departing RWY 19, at 600FT turn due to terrain.

**CTAF** 127.55**NOISE ABATEMENT PROCEDURES**

1. No circuits below 1,000 FT.
2. RWY 01 - make wide left circuit to reduce noise to Murwillumbah Hospital.

**ADDITIONAL INFORMATION**

1. PJE HJ 1.5NM NW of the airfield.
2. Bird hazard exists.
3. RWY subject to flooding during high rain/Tweed River flooding events.
4. All areas may be unusable due SWS after rain. Airfield not inspected.
5. Cleared areas outside gable markers mown, taxi at pilot risk.

**CHARTS RELATED TO THE AERODROME**

WAC 3357.