SUNRISE DAM

FLFV 1350

AVFAX CODE 6109 ظےWA

↑ 355° 28.5NM

Laverton

UTC +8 290554S 1222719F

VAR 1 DEG E

YSRD CFRT

AD OPR Anglogold Ashanti Australia Ltd - GPO Box F377, Perth. WA. 6001. Email: inflightess@anglogoldashanti.com, PH 08 9080 3765 (BH). ARO 0437 413 119 (H24).

REMARKS

Restricted OPS: PPR from AD OPR.

HANDLING SERVICES AND FACILITIES

JET A1 private installation, Contact National Jet Express, PH 08 8154 7444.

PAL 120.25

Email: rsgroundops@nie.aero.

PHYSICAL CHARACTERISTICS

06/24 059 64a PCR 250/F/B/Y/T WID 30 **RWS 150**

AFRODROME AND APPROACH LIGHTING

RWY 06/24 LIRI PAI 120.25 SDBY PWR AVBL BY

PRIOR

ARRANGEMENT

SDBY PWR AVBL BY

PRIOR

3.0 DEG49FT

ARRANGEMENT BY PRIOR

RWY 06/24 PTBL(1) ARRANGEMENT

(1) EMERG only. 90MIN PN.

RWY edge light spacing: 59M. 1.

PAPI

2 SDBY PWR is manually activated, 3HR PN for activation.

OTHER LIGHTING TWY LGT: Blue edge.

RWY 06/24

ATS AND AERODROME COMMUNICATION FACILITIES

FIA MELBOURNE CENTRE 118.4 3.500FT

LOCAL TRAFFIC REGULATIONS

RWY 06/24 - RWY end turning nodes - all turns must be MNM speed MAX RAD.

FLIGHT PROCEDURES

ACFT to avoid flying over mine pit.

CTAF - AFRU 126.8

AFRU signal not AVBL on ground Laverton, Murrin Murrin or Sunrise Dam. AFRU located at

ADDITIONAL INFORMATION

- 1 Bird Hazard in VCY of AD (falcons or hawks).
- Animal hazard (kangaroos), ARO will conduct additional RWY inspection prior to scheduled 2. ACFT OPS.
- 3. Seasonal wetlands may be present at western end of RWY, ducks, swans and birds of prey maybe in VCY.

CHARTS RELATED TO THE AERODROME

- WAC 3352. 1.
- 2. Also refer to AIP Departure and Approach Procedures.