


**TYABB****ELEV 88****FULL NOTAM SERVICE NOT AVBL**

VIC UTC +10 YTYA  
 S 38 16.0 E 145 10.5 VAR 12 DEG E UNCR  
 AD OPR Peninsula Aero Club, Stuart Road, Tyabb, VIC, 3913. Email:  
 pac@pac.asn.au. PH 03 5977 4406. PH AH 0413 605 937. Fax 03 5977  
 4874.

**REMARKS**

1. PPR from PAC Flight Operations for all visiting ACFT
2. Parking for visiting ACFT is limited, arrange with Flight Operations when calling for permission.
3. AD charges: Commercial OPS and overnight parking. \$5/engine donation private OPS.
4. RWY 17/35 sealed with grass shoulders.

**HANDLING SERVICES AND FACILITIES**

AVGAS AVBL H24. Credit card only.

**UNICOM**

1. 128.0 - OPR: Peninsula Aero Club, HR 0900 - 1700 Local Time.
2. Permission to OPR is not AVBL on UNICOM.
3. UNICOM occasionally not manned.

**PHYSICAL CHARACTERISTICS**

RWY 17/35 1,000M. Unrated Sealed

RWY 08/26 600M. Unrated Grass

**ATS COMMUNICATIONS FACILITIES**

FIA MELBOURNE CENTRE 135.7 Circuit Area

**LOCAL TRAFFIC REGULATIONS**

1. Circuit training is not permitted for visiting ACFT.
2. RH circuit required on RWY35 and RWY08.
3. Use RWY08 and RWY26 only when operationally required.
4. Preferred RWY17.
5. Pilots are reminded to avoid low approaches to RWY17 due to proximity to Mornington-Tyabb Road.
6. Taxiing IFR ACFT can contact MELBOURNE CENTRE 120.0.

**CTAF - AFRU 128.0****NOISE ABATEMENT PROCEDURES**

1. Avoid overflying Tyabb, Somerville and Hastings townships below 2,000FT AMSL unless operationally required.
2. ACFT joining and operating in the circuit should avoid flying over Tyabb township.
3. Helicopters:
  - a. Circuits permitted to WEST of airport at 1,000FT AMSL but must remain EAST of Boes Road;
  - b. Circuits to EAST of aerodrome at 1,100FT AMSL;
  - c. Helicopters are requested to vary arrival and departure tracks.
4. The full noise abatement procedures can be found at <http://pac.asn.au/fly-neighbourly>.

**CHARTS RELATED TO THE AERODROME**

WAC 3469, 3470.