

**AIP SUPPLEMENT
(SUP)****H45/22****Effective: 202205050100 UTC**AERONAUTICAL INFORMATION SERVICE,
AIRSERVICES AUSTRALIA, GPO BOX 367,
CANBERRA ACT 2601For **DISTRIBUTION** queries, contact:
Email: aim_editorial@airservicesaustralia.comFor **CONTENT** queries regarding this SUP, contact:
Email: smerlo@hobartairport.com.au**HOBART AIRPORT (YMHB) FREIGHT APRON
PARKING BAY RE-NUMBER****1. INTRODUCTION**

- 1.1 This SUP cancels and replaces SUP H23/22 with changes made to paras 2.5.1 and 2.5.2.
- 1.2 This SUP outlines the AIP publication changes as a result of Hobart Airport Freight Apron line marking works. It intends to provide notification to pilots of significant changes to parking position designators, alignment and associated lead-in lead-out line markings on the Hobart Airport freight apron.

2. WORKS PROGRAM

- 2.1 Works will be carried out in accordance with YMHB MOWP 2206.

2.2 Stage 1

- 2.2.1 Between 202205012200 and 202205021000 UTC will only consist of surveying new line markings associated with the changes to the Bays. During stage 1 there will be no changes to Bay positions or markings.

2.3 Stage 2

- 2.3.1 Between 202205022200 and 202205031000 UTC existing Bays 11A and 11B will be removed and new Bays 12 and 13 installed. Existing bays 9, 9B and 10 available.
- 2.3.2 Between 202205031001 and 202205032159 UTC new Bays 12 and 13 and existing bays 9, 9B and 10 available. See Appendix 3.

2.4 Stage 3

- 2.4.1 Between 202205032200 and 202205041000 UTC existing Bay 10 will be renumbered Bay 11. New Bays 12 and 13 not available. Existing Bays 9 and 9B will available.
- 2.4.2 Between 202205041001 and 202205042159 UTC new Bays 11, 12 and 13 and existing bays 9, 9B available. See Appendix 4.

2.5 Stage 4

- 2.5.1 Between 202205082200 UTC and 202205091000 UTC existing Bay 9B will be renumbered Bay 10 and existing Bay 9 moved. New Bays 12 and 13 available. Existing Bays 9, 9B and new bay 11 will not available.
- 2.5.2 From 202205091001 UTC new Bays 9, 10, 11, 12 and 13 available. See Appendix 5.

3. OPERATIONAL INFORMATION

- 3.1 During Stage 4 the grass GA parking area adjacent to the freight apron will not be available.
- 3.2 The apron can be made available to emergency service helicopters on 30 minute prior notice.

3.3 Bay re-designation

Current Bay Number	Re-designated Bay Number
9	No change
9A	Removed
9B	10
9C	Removed
10	11
11B	12
11A	13

- 3.4 Further details can be found in MOWP YMHB2206 or by contacting operations@hobartairport.com.au.

3.5 Final parking position coordinates

Designator	Latitude	Longitude	Elevation (FT)	Capacity	Docking System	Fuel
9	425021.30S	1473026.80E	12	B738	Marshaller	Tanker
10	425021.49S	1473026.31E	12	C130	Marshaller	Tanker
11	425023.31S	1473024.01E	12	B738	Marshaller	Tanker
12	425024.29S	1473023.17E	12	B350	Pilot Stop Bar	Tanker
13	425024.75S	1473023.92E	12	B350	Pilot Stop Bar	Tanker

4. CONTACT INFORMATION

4.1 For additional information or clarification of information contained within this SUP, contact:

Sam Merlo

Operations Compliance Coordinator

Hobart Airport

PH: +61 3 6216 1600

Email: smerlo@hobartairport.com.au

5. CANCELLATION

5.1 This SUP will be cancelled when it is incorporated into AIP DAP, expected to be in DAP Amendment 172, effective 8 September 2022.


6. DISTRIBUTION

6.1 Airservices Australia website only.


Appendices

1. Scope of works
2. Works staging
3. Stage 2
4. Stage 3
5. Stage 4


1. Scope of works




2. Works staging



3. Stage 2



4. Stage 3



5. Stage 4

