
13 JUN 2024

GOLD COAST SIX DEPARTURE (RADAR) - RWY 14, 17 & 32 GOLD COAST, QLD (YBCG)



GOLD COAST SIX DEPARTURE (RADAR)

RWY 14

- Track 139°
- NON-JET ACFT AT or ABV 600ft but not before 1 DME turn to assigned heading or track JET ACFT - AT or ABV 600ft but not before 2 DME turn to assigned heading or track.
- When directed, Contact BN Approach for Radar Vectors.

RWY 17

- Track 173°
- AT or ABV 1000ft but no later than 3 DME turn to assigned heading or track.
- When directed, Contact BN Approach for Radar Vectors

RWY 32

- Track 319°
- AT or ABV 600ft but not later than 2 DME, turn to assigned heading or track.
- When directed, Contact BN Approach for Radar Vectors

COMMUNICATIONS FAILURE PROCEDURE

On recognition of communication failure:

- Squawk 7600.
- Maintain last assigned vector for two minutes and, if necessary, climb to minimum safe altitude to maintain terrain clearance, then
- Proceed in accordance with the latest ATC route clearance acknowledged.

Changes: CAUTION NOTE, Editorial.

BCGDP01-179

