


**27 NOV 2025**

**USE QNH**

**HAMILTON ISLAND, QLD (YBHM)**



## NOTES

1. PROC AVBL up to MLW.
2. Lateral transition to MAP must not be initiated prior to DA/H PSN.
3. APCH Path does not coincide with PAPI glide path 3°.
4. Transient yacht masts may infringe RWY 14 visual approach slope clearance.
5. See Engineering Report for Minimum MAP gradient (AE) to 2800 FT.

| CATEGORY   | A              | B | C                            | D |
|------------|----------------|---|------------------------------|---|
| RNP (0.30) | NOT APPLICABLE |   | DA(H) <b>669'</b> (655')-3.7 |   |
| CIRCLING   |                |   | NOT AUTHORISED               |   |

202507181007 General Electric Company Proprietary & Confidential Information

Revision: Editorial.

BHMGN03-185

DO NOT USE FOR NAVIGATION

Prepared by GE Aerospace

