
STANDARD INSTRUMENT DEPARTURES (SID) ROCKHAMPTON THREE DEPARTURE (RADAR) RWY 15 & 33



ROCKHAMPTON THREE DEPARTURE (RADAR)

RWY 15

- GRAD 3.3%
- Track 148°

10 NM MSA 3200

AT 1300ft turn to assigned heading or track

RWY 33

- GRAD 3.4% to 2500ft, then 3.3%
- Track 328°
- AT 1300ft turn to assigned heading or track

COMMUNICATIONS FAILURE PROCEDURE

On recognition of communications failure

- Squawk 7600
- Maintain last assigned vector for two minutes, and
- CLIMB IF NECESSARY TO MINIMUM SAFE ALTITUDE, to maintain terrain clearance, then
- proceed in accordance with the latest ATC route clearance acknowledged.

BRKDP01-183



© Airservices Australia