

EAST SALE FIVE DEPARTURE (RADAR)

RWY 04

GRAD 3.3%

- Track 041°
- At 2000ft, but not before DER, turn to assigned heading or track

RWY 09

GRAD 3.3%

- Track 086°
- · At 2000ft, but not before DER, turn to assigned heading or track

RWY 22

GRAD 3.6% to 1200ft then 3.3%

- Track 221°
- · At 2000ft, but not before DER, turn to assigned heading or track

RWY 27

GRAD 3.3%

- Track 266°
- At 2000ft, but not before DER, turn to assigned heading or track

COMMUNICATIONS FAILURE PROCEDURE

On recognition of communication failure

- Squawk 7600
- · Maintain last assigned vector for two minutes, and
- CLIMB IF NECESSARY TO MINIMUM SAFE ALTITUDE, to maintain terrain clearance, then

airservices

• proceed in accordance with the latest ATC route clearance acknowledged.

Changes: AFIS REMOVED, Editorial.

