BINDOON HILL **FLFV 925 FULL NOTAM SERVICE NOT AVBL**

WA UTC +8 312025S 1161118E VAR 1 DEG W **UNCR**

AD OPR Superlight Aircraft Club of WA, PO Box 293, Bindoon, WA, 6502, Email: secretary@slacwa.org.au, PH AD MGR 0492 930 303.

REMARKS

- 1. PPR.
- 2. Previously known as Bindoon Abandoned.
- 3. See SLACWA Standard Operating Procedures at www.slacwa.org.au.
- AD located within R155B.

HANDLING SERVICES AND FACILITIES

Nil fuel AVBL.

PHYSICAL CHARACTERISTICS

46a/c Unrated. Bitumen and gravel. RWY LEN 09/27 **WID 40** 1,400M, 900M FM RWY 09 THR bitumen.

ATS AND AERODROME COMMUNICATION FACILITIES

MELBOURNE CENTRE 120.3

LOCAL TRAFFIC REGULATIONS

Carriage and use of radio is required by AD OPR.

FLIGHT PROCEDURES

Right hand circuits RWY 27, avoid overflying houses on south side of Dewars Pool Rd, permission RQ before use.

CTAF 126.7

ADDITIONAL INFORMATION

- Recreational aircraft club, ultralights, motor gliders, homebuilts, vintage, gryroplanes. helicopters, trikes and powered parachutes.
- 2. Further information contact ARO.
- AD is published on Perth VNC

CHARTS RELATED TO THE AERODROME

WAC 3351, 3462,