COOMA - SNOWY MOUNTAINS Δ 113

VFAX CODE	E 2113
84	NSW
Ratar ERGA RDS	361802S
	AD OPR
· · · · · · · · · · · · · · · · · · ·	Jindabyne
048° 9NM	H24 0415
Cooma	

UTC +10 1485826E VAR 13 DEG E YCOM

ELEV 3106

CERT

D OPR General Manager. Snowy Mountains Airport - Cooma. PO Box 35.

ndabyne. NSW. 2627. Email: aviation@snowymountainsairport.com.au. ARO 24 0415 582 069.

REMARKS

- 1. AD Charges (All exclude GST):
 - \$15.00/tonne MNM \$15.00 for single engined ACFT,
 - \$30 for other ACFT. Helicopters and Ultra-lights:
 - \$7.50/tonne MNM charge \$7.50. Night landing fee: \$30.00 from 2000 Local. Over night parking: \$15.00/night - \$45.00/week.

Commercial charters: 5 or more PAX - PAX tax \$12.50/PAX arriving and departing. Tonnage fee or PAX tax apply - which ever is higher. Charter flight require PN.

This AD is a Security Controlled Airport.

HANDLING SERVICES AND FACILITIES

Nil fuel AVBL.

PASSENGER FACILITIES

2.

TX - 02 6452 7777 (taxi's travel from Cooma township)/LG and RF - AVBL HS/WC - H24.

AERODROME OBSTACLES

Lit hazard lights:

- a. 3,775FT AMSL BRG 334 DEG MAG 5,056M FM ARP. Obstructs inner HZS by 559.06FT. Flashing.
- 3.558FT AMSL BRG 111 DEG MAG 2.284M FM ARP. Obstructs inner HZS by b. 342.52FT. Flashing.
- 3.270FT AMSL BRG 352 DEG MAG 3.616M FM ARP. Obstructs RWY 36 TKOF climb C. SFC by 63.65FT.
- d. 3,223FT AMSL BRG 358 DEG MAG 3,698M FM ARP. Obstructs RWY 36 TKOF climb SFC by 8.53FT.
- e. 3.248FT AMSL BRG 002 DEG MAG 3.944M FM ARP. Obstructs RWY 36 TKOF climb SFC by 17.72FT.

METEOROLOGICAL INFORMATION PROVIDED

- TAF CAT D. METAR/SPECI. 1.
- 2. AWIS PH 02 9353 6414 - Report faults to BoM.

PHYSICAL CHARACTERISTICS

18/36 180 70a PCN 12/F/A/0.65 MPa/T WID 30 **RWS 150** AERODROME AND APPROACH LIGHTING RWY 18/36 I IRI AFRU+PAL 118.1 SDBY PWR AVBL RWY 18/36 PAPI(1) AFRU+PAL 118.1 3.0 DEG40FT SDBY PWR AVBL (1)Left side. Lighting status confirmed on PAL.

RWY edge light spacing: 18/36: 60M.

OTHER LIGHTING

HBN

HBNs: Located NNW and SE of AD.

SDBY PWR supplies by AD generator in the event of mains PWR failure. 1.

2. TWY LGT: Blue edge.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA	MELBOURNE CENTRE	120.75 Circuit area (On ground COM contact
		119.4)

RADIO NAVIGATION AND LANDING AIDS

DME	COM	114.0/ 87X	362115.5S	1485727.7E		(1)
NDB	COM	293	362113.6S	1485727.1E	Range 80 (HN 70)	(2)

- (1) Antenna ELEV 3026FT.
- (2) 003/3.3 to ARP.

LOCAL TRAFFIC REGULATIONS

1. Parking restrictions

- a. To avoid OBST to RPT ACFT, parking for GA ACFT BLW 5,700KG MTOW AVBL E and ADJ to RPT Bay 3 and 3A.
- b. ACFT parking in RPT bays require PN on Monday, Thursday, Friday 0800-1800 Local.
- c. RPT Bays 1 and 2 suitable up to DH8D.
- d. RPT Bays 1A and 2A suitable up to SF34.
- e. RPT Bays 3 and 3A suitable up to JS32.

2. RWY 18/36 turning restrictions

- a. Pilots to use full RWY width when turning (no sharp turns).
- b. ACFT ABV 5,700KG MTOW must only turn at the turn pads.

CTAF - AFRU 118.1

ADDITIONAL INFORMATION

- 1. Bird and animal hazard exists.
- Gliders OPR FM Bunyan Airstrip 12.5NM NE Cooma HJ, generally JF, and monitor 122.7, or CTAF when WI 10NM of Cooma AD. Tug ACFT when airborne monitor CTAF and 122.7.
- 3. Polo Flat airfield located adjacent to Cooma Township and 9NM NE of Cooma Snowy Mountains AD. Polo Flat has a separate ERSA entry.
- 4. Risk of snowfall or heavy frost year-round. Highest risk from May to October. No snow clearing or de-icing equipment AVBL.

CHARTS RELATED TO THE AERODROME

- 1. WAC 3470.
- 2. Also refer to AIP Departure and Approach Procedures.