CRESSY FLFV 420


FULL NOTAM SERVICE NOT AVBL

 VIC
 UTC +10
 YCRE

 380224S
 1433911E
 VAR 11 DEG E
 UNCR

AD OPR CSS Investments, 175 Aerodrome Road, Cressy, VIC, 3320. Email:

cressyaerodrome@iinet.net.au. PH 0481 327 587.



REMARKS

PPR.

HANDLING SERVICES AND FACILITIES

No fuel AVBL.

PASSENGER FACILITIES

WC/RF/HC/AC.

AERODROME OBSTACLES

- Powerlines on the approach to RWY 33.
- Unlit TWY 355 DEG MAG 0.8NM FM ARP.

PHYSICAL CHARACTERISTICS

01/19 36c Unrated. Grass. RWY LEN 1,100M WID 50 15/33 30c Unrated. Grass. RWY LEN 900M WID 50

AERODROME AND APPROACH LIGHTING

RWY 01/19 PTBL(1) BY PRIOR ARRANGEMENT

30MIN PN.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA MELBOURNE CENTRE 126.8

FLIGHT PROCEDURES

- Right hand circuits when operating on RWY 01 and 33.
- Pilots are encouraged to avoid overflying Cressy township and properties to the S.
- Aircraft approaching from NW or W to track via Lake Rosine and when approaching from S
 track via the eastern shore of Lake Weering.

CTAF 126.7

ADDITIONAL INFORMATION

Railway tracks are close to the threshold of RWY 15 and 19.

CHARTS RELATED TO THE AERODROME

WAC 3469.