

CRESSY

ELEV 420

FULL NOTAM SERVICE NOT AVBL

VIC

UTC +10

YCRE


380224S

1433911E

VAR 11 DEG E

UNCR

AD OPR CSS Investments, 175 Aerodrome Road, Cressy, VIC, 3320. Email: cressyaerodrome@iinet.net.au. PH 0481 327 587.



REMARKS

PPR.

HANDLING SERVICES AND FACILITIES

No fuel AVBL.

PASSENGER FACILITIES

WC/RF/HC/AC.

AERODROME OBSTACLES

- 1. Powerlines on the approach to RWY 33.
- 2. Unlit TWY 355 DEG MAG 0.8NM FM ARP.

PHYSICAL CHARACTERISTICS

01/19	36c	Unrated. Grass. RWY LEN 1,100M	WID 50
15/33	30c	Unrated. Grass. RWY LEN 900M	WID 50

AERODROME AND APPROACH LIGHTING

RWY 01/19	PTBL(1)	BY PRIOR ARRANGEMENT
-----------	---------	----------------------

- (1) 30MIN PN.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA	MELBOURNE CENTRE	126.8
-----	------------------	-------

FLIGHT PROCEDURES

- 1. Right hand circuits when operating on RWY 01 and 33.
- 2. Pilots are encouraged to avoid overflying Cressy township and properties to the S.
- 3. Aircraft approaching from NW or W to track via Lake Rosine and when approaching from S track via the eastern shore of Lake Weering.

CTAF 126.7

ADDITIONAL INFORMATION

- 1. Railway tracks are close to the threshold of RWY 15 and 19.
- 2. Kangaroo hazard may exist.

CHARTS RELATED TO THE AERODROME

WAC 3469.