YMBD

UNCR

MURBAY BRIDGE AVEAX CODE 5019

ELEV 157 FULL NOTAM SERVICE NOT AVBL

UTC +9:30 1391336E VAR 8 DEG E AD OPR Comak Ptv Ltd. PO Box 88. Aldgate, SA, 5154. Email:

vmbdairfield@gmail.com. PH 0408 841 066. Website:

www.murravbridgeairfield.com.au.

REMARKS 1.

- Private AD, PPR Contact ARO 0900-1700 Local for permission.
- Operations should be in accordance with the Airport User Manual and information on the aerodrome website.
- 3 AD charges: apply for non-resident ACFT. Refer to AD website for details.

HANDLING SERVICES AND FACILITIES

2.

SA

350352S

AVGAS H24 self-serve swipe bowser on main apron. Credit card (MC and V only).

PASSENGER FACILITIES

WC.

APRONS AND TAXIWAYS

- 1. Main APN: bitumen, Restricted to 5,700KG MTOW.
- TWY A and TWY B: 9M wide. Sealed. Bitumen. Restricted to 5,700KG MTOW. 2
- 3. TWY C: grass.
- 4. Maximum tyre pressure for APN and sealed TWY: 850kPa/ 120PSI.

METEOROLOGICAL INFORMATION PROVIDED

TAF CAT D. METAR/SPECI.

PHYSICAL CHARACTERISTICS

02/20 5700 kg/0.85 MPa Sealed. RWY 20 THR 90M **WID 18** 39a FM start of sealed strip. RWY 02 THR 60M FM start of sealed strip. RWY LEN 1,200M. Slope 0.4% down to N. 09/27 26c Unrated, Grass, RWY LEN 790M, Slope 2% down to E. **WID 30**

AERODROME AND APPROACH LIGHTING

RWY 02/20 LIRL(1)

BY PRIOR ARRANGEMENT

ACT by PAL. PPR FM AD OPR. (1)

ATS AND AERODROME COMMUNICATION FACILITIES FIA 130.45 Circuit Area

ADELAIDE CENTRE

LOCAL TRAFFIC REGULATIONS

- 1. Carriage and use of radio is required by AD OPR.
- ACFT taking off RWY 27 are not visible from THR RWY 02/20. 2.
- 3. No straight in approaches or joins on the base leg when other traffic is using the circuit.
- Expect LDG motor-gliders to exit RWY 02/20 via TWY B due to wingspan. 4.

CTAF 127.5

ADDITIONAL INFORMATION

- 1. Beware of circuit traffic at Rollo's (YRLO) located 2.5NM to NW.
- 2. CTAF shared with Rollo's (YRLO) and Callington (YCTO).
- D285 for aerobatic activity, SFC-4000FT, activated by NOTAM. 3.
- Aerobatic area within 1,000M E and adjacent to RWY 02/20, may occur with prior approval 4. FM the ARO. During aerobatics in this area E from RWY 02/20, the pilot will broadcast intentions on the CTAF, crosswind joins are not recommended and RWY 09/27 will not be available.
- 5. Pilots are requested to avoid overflying Monarto Zoo (4NM WSW of ARP) below 2,000FT AMSL and avoid overflying the farm building complex (0.8NM ESE of ARP) below 1,200FT AMSL.
- Intense flying training activity at and in the vicinity of the aerodrome. 6.
- Glider operations at aerodrome. 7.

CHARTS RELATED TO THE AERODROME WAC 3458.