

21

90

24

35

120°

1.5NM

Maryborough

35

VIC

370159S

1434232E

UTC +10

VAR 11 DEG E

YMBU

UNCR

MARYBOROUGH (VIC)

ELEV 766

FULL NOTAM SERVICE NOT AVBL

AD OPR Central Goldfields Shire Council, 22 Nolan Street, Maryborough,
3465. Email: mail@cgoldshire.vic.gov.au. PH 03 5461 0610.
Fax 03 5461 0666.

REMARKS
AD not AVBL to ACFT ABV 5,700KG MTOW.

PASSENGER FACILITIES
WC/TX (03 5461 1633)/RF/LG (Access Code C19; turn knob clockwise).

AERODROME OBSTACLES
Trees in the vicinity of runway may impact the approach or departure of aircraft.

PHYSICAL CHARACTERISTICS

06/24	21	5700 kg/0.45 MPa Unrated. Gravel	WID 30	RWS 90
17/35	34a/b	5700 kg/0.65 MPa Unrated. Sealed	WID 30	RWS 90

AERODROME AND APPROACH LIGHTING
RWY 17/35 LIRL AFRU+PAL 119.1
RWY edge light spacing: 17/35: 87M.

ATS AND AERODROME COMMUNICATION FACILITIES
FIA MELBOURNE CENTRE 126.8 Circuit Area

LOCAL TRAFFIC REGULATIONS

- Circuit training not permitted 2200-0700 Local.
- ACFT on different RWY may not be visible to each other.
- HLS FATO/TKOF 35M diameter. HLS MTOW unlimited.
- Radios to be carried and used.

FLIGHT PROCEDURES
Right hand circuit RQ when OPR on RWY 17 and 24.

CTAF - AFRU 119.1

ADDITIONAL INFORMATION

- Bird hazard exists.
- Kangaroos may be on RWY - pilots should conduct a flyover before landing.

CHARTS RELATED TO THE AERODROME
WAC 3469.

Information may be continued on the next page: PTO