

21

90

24

35

120°

1.5NM

Maryborough

VIC

370159S

1434232E

AD OPR Central Goldfields Shire Council, 22 Nolan Street, Maryborough, 3465. Email: mail@cgoldshire.vic.gov.au. PH 03 5461 0610. Fax 03 5461 0666.

REMARKS

AD not AVBL to ACFT ABV 5,700KG MTOW.

PASSENGER FACILITIES

WC/TX (03 5461 1633)/RF/LG (Access Code C1191)

AERODROME OBSTACLES

Trees in the vicinity of runway may impact the approach or departure of aircraft.

ELEV 766

FULL NOTAM SERVICE NOT AVBL

UTC +10

YMBU

VAR 11 DEG E

UNCR

PHYSICAL CHARACTERISTICS

06/24

21

5700 kg Unrated. Gravel

WID 30

RWS 90

17/35

34a/b

5700 kg Unrated. Sealed

WID 30

RWS 90

AERODROME AND APPROACH LIGHTING

RWY 17/35

LIRL

AFRU+PAL 119.1

RWY edge light spacing: 17/35: 87M.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA

MELBOURNE CENTRE

126.8 Circuit Area

LOCAL TRAFFIC REGULATIONS

1.

Circuit training not permitted 2200-0700 Local.

2.

ACFT on different RWY may not be visible to each other.

3.

HLS FATO/TKOF 35M diameter. HLS MTOW unlimited.

4.

Radios to be carried and used.

FLIGHT PROCEDURES

Right hand circuit RQ when OPR on RWY 17 and 24.

CTAF - AFRU 119.1

ADDITIONAL INFORMATION

1.

Bird hazard exists.

2.

Kangaroos may be on RWY - pilots should conduct a flyover before landing.

CHARTS RELATED TO THE AERODROME

WAC 3469.

Information may be continued on the next page: PTO