MELTON

FLFV 670 FULL NOTAM SERVICE NOT AVBL



VIC

1443356E

UTC +10 VAR 11 DEG E

373718S UNCR AD OPR E. Reeve. 995 Coburns Road. Toolern Vale. VIC. 3337. Email: info@meltonairservices.com.au. PH 03 9746 1342. Website:

www.meltonairservices.com.au.

RFMARKS

PPR - Contact Melton Air Services. PH AD OPR.

HANDLING SERVICES AND FACILITIES

AVGAS AVBL, CTC AD OPR, Cash, V and MC accepted.

PASSENGER FACILITIES

LG/WC/RF/TX/ME.

PHYSICAL CHARACTERISTICS

04/22	44c	Unrated. Grass/Gravel. RWY LEN 1,340M.	WID 30	RWS 60
		RWY 22 DTHR 90M. Slope 1% down to SW.		
10/28	33c	Unrated. Grass. RWY LEN 1,000M.	WID 30	RWS 60
		RWY 28 DTHR 90M. Slope 1% down to SE.		
14/32	39c	Unrated. Grass. RWY LEN 1,200M.	WID 30	RWS 60
		Slope 1% up to N.		
16/34	21c	Unrated, Grass, RWY LEN 650M.	WID 30	
		Slope 1% up to N.		

AERODROME AND APPROACH LIGHTING

RWY 04/22 LIRI BY PRIOR ARRANGEMENT

RWY 04/22 edge light spacing: 89M.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA MELBOURNE CENTRE 135.7 Circuit Area

LOCAL TRAFFIC REGULATIONS

All ACFT DEP (other than touch and go OPS) to commence take off roll from RWY end to maximise height over residential areas after take off.

FLIGHT PROCEDURES

- Where possible, ACFT should conform to established RWY direction. 1.
- 2. Arrivals - at least 3 leas of the circuit to be flown.
- 3. Straight in approaches are not permitted.
- 4. RH Circuits RWY 04 and 10.
- 5. Landings only RWY 34.
- Take off/landing RWY 16 not permitted.
- All ACFT to avoid overflying Toolern Vale township NE of aerodrome.

CTAF 121.6

CHARTS RELATED TO THE AERODROME

WAC 3469, 3470,