


MURRAY FIELD**ELEV 56****AVFAX CODE 6010****FULL NOTAM SERVICE NOT AVBL**

WA 323037S 1155000E UTC +8 YMUL
 VAR 2 DEG W UNCR
 AD OPR Royal Aero Club of WA, 41 Eagle Drive, Jandakot Airport, WA,
 6164. Email: info@royalaeroclubwa.com.au. PH 08 9417 0000. ARO 08
 9581 6222. Fax 08 9417 0040.

REMARKS

1. Restricted OPS. PPR from AD OPR.
2. LDG fees applicable.

HANDLING SERVICES AND FACILITIES

AVGAS AVBL for RACWA OPS. Non RACWA OPS AVBL by appointment 24HR PN. Not AVBL MON.

AERODROME OBSTACLES

Numerous high voltage powerlines surround the aerodrome to the N and E.

PHYSICAL CHARACTERISTICS

05/23	38a	5700 kg/0.70 MPa Sealed. RWS 90	RWY LEN 1,159M.	WID 18	RWS 90
		Slope 0.25% down to SW.			
09/27	30c	5700 kg Unrated. RWS 60	RWY LEN 903M.	WID 15	RWS 60
		Slope 0.22% down to W.			

AERODROME AND APPROACH LIGHTING

RWY 05/23 LIRL AFRU+PAL 119.1

ATS AND AERODROME COMMUNICATION FACILITIES

FIA PERTH CENTRE 135.25 Circuit Area

FLIGHT PROCEDURES

Right hand circuits RWY 05 and RWY 09.

CTAF - AFRU 119.1**NOISE ABATEMENT PROCEDURES**

1. Circuit training permitted only BTN 0700-2200 Local.
2. RWY 27 - TKOF not available (Emergency only).
3. HEL OPS not permitted west of RWY 05/23. HEL CCTS not permitted RWY 09/27.
4. CCTS restricted to ACFT not exceeding 200 horsepower.

ADDITIONAL INFORMATION

1. Animal hazard exists.
2. CAUTION: Low level aerobatics are conducted within 1NM of AD.
3. PJE occur HJ on airfield up to FL150. Pilots advised to monitor CTAF and PH CEN for DZ status.

CHARTS RELATED TO THE AERODROME

WAC 3462.