


**SERPENTINE****ELEV 30****FULL NOTAM SERVICE NOT AVBL**

WA  
322342S 1155224E  
AD OPR Sport Aircraft Builder's Club of WA Inc, Yangedi Road North,  
Hopeland, WA, 6125. Email: [secretary@sabc.org.au](mailto:secretary@sabc.org.au). PH Club  
House 08 9525 2085 (not always manned). Website: [www.sabc.org.au](http://www.sabc.org.au).

UTC +8  
VAR 2 DEG W

YSEN  
UNCR

**REMARKS**

1. PPR.
2. Helicopter OPS 24/7.

**AERODROME OBSTACLES**

1. High voltage powerlines intersects APCH slope 500M to West of THR 05.
2. Trees to 10M short final 27.

**PHYSICAL CHARACTERISTICS**

05/23	30a	Unrated. Sealed. RWY LEN 900M.	WID 12	RWS 15
		RWY 23 DTHR 100M.		
09/27	20c	Unrated. Grass. RWY LEN 600M.	WID 24	RWS 30

**AERODROME AND APPROACH LIGHTING**

RWY 05/23 MIRL PAL 125.3

RWY 05/23 edge LGT spacing: 96M.

**ATS AND AERODROME COMMUNICATION FACILITIES**

FIA PERTH CENTRE 135.25 On ground

**LOCAL TRAFFIC REGULATIONS**

ACFT should manoeuvre on TWY and RWY only due to soft sand.

**FLIGHT PROCEDURES**

1. RWY 05 MNM CCT HGT 1,000FT.
2. CCTS not permitted before 0800 on SUN.

**CTAF** 119.1

**ADDITIONAL INFORMATION**

1. RWY 09/27 grass RWY sprinklers may be operating during summer months.
2. Murray Field AD has identical RWY numbers and CTAF.
3. Kangaroo and bird hazard exists all areas.
4. Low level aerobatics in VCY.
5. Perth VTC and VNC.

**CHARTS RELATED TO THE AERODROME**

WAC 3462.