


SUNRISE DAM

ELEV 1350

AVFAX CODE 6109



WA

290554S

1222719E

UTC +8

VAR 1 DEG E

YSRD

CERT

AD OPR Anglogold Ashanti Australia Ltd - GPO Box F377, Perth, WA, 6001. Email: inflightess@anglogoldashanti.com. PH 08 9080 3765 (BH). ARO 0437 413 119 (H24).

REMARKS
Restricted OPS: PPR from AD OPR.

HANDLING SERVICES AND FACILITIES

JET A1 private installation. Contact National Jet Express, PH 08 8154 7444.
Email: rsgroundops@nje.aero.

PHYSICAL CHARACTERISTICS

06/24	059	64a	PCR 250/F/B/Y/T	WID 30	RWS 150
-------	-----	-----	-----------------	--------	---------

AERODROME AND APPROACH LIGHTING

RWY 06/24	LIRL	PAL 120.25			SDBY PWR AVBL BY PRIOR ARRANGEMENT
RWY 06/24	PAPI	PAL 120.25	3.0 DEG49FT		SDBY PWR AVBL BY PRIOR ARRANGEMENT
RWY 06/24	PTBL(1)				BY PRIOR ARRANGEMENT

- (1) EMERG only. 90MIN PN.
1. RWY edge light spacing: 59M.
2. SDBY PWR is manually activated. 3HR PN for activation.

OTHER LIGHTING

TWY LGT: Blue edge.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA MELBOURNE CENTRE 118.4 3,500FT

LOCAL TRAFFIC REGULATIONS

RWY 06/24 - RWY end turning nodes - all turns must be MNM speed MAX RAD.

FLIGHT PROCEDURES

ACFT to avoid flying over mine pit.

CTAF - AFRU 126.8

AFRU signal not AVBL on ground Laverton, Murrin Murrin or Sunrise Dam. AFRU located at Leonora.

ADDITIONAL INFORMATION

- Bird Hazard in VCY of AD (falcons or hawks).
- Animal hazard (kangaroos). ARO will conduct additional RWY inspection prior to scheduled ACFT OPS.
- Seasonal wetlands may be present at western end of RWY, ducks, swans and birds of prey maybe in VCY.

CHARTS RELATED TO THE AERODROME

- WAC 3352.
- Also refer to AIP Departure and Approach Procedures.