
THUNDERBOX **AVEAX CODE 6116**

FLFV 1704

WA UTC +8 280914S 1205621F VAR 1 DEG E YTHN **CFRT**

AD OPR Northern Star (Thunderbox), Locked Bag 2, Leonora, WA, 6438, Email: tboaerodrome@nsrltd.com, PH 08 6228 9500, AD Manager PH 0428 666 673, Email: alabrown@nsrltd.com, ARO H24 0483 188 518. Website: www.nsrltd.com.



REMARKS

- PPR from AD OPR.
- 2. AD AVBL HJ only EXC for EMERG.

HANDLING SERVICES AND FACILITIES

Ground handling and fuel (JET A1) by prior arrangement with AD OPR.

PASSENGER FACILITIES

WC.

AERODROME OBSTACLES

- Fence parallel to RWY CL, 53M S of RWY CL, infringes transitional SFC by 2FT.
- 2. Mine site BRG 119 DEG MAG 4.5NM FM ARP.
- 3. Unmarked and unlit mast 1.893FT AMSL BRG 068 DEG MAG 2.8NM FM ARP, infringes conical SFC by 40FT.
- Trees located parallel to RWY 07/25 CL, EXTD APRX 100M N, 100M S and along full 4. length of RWY. Infringes transitional SFC by up to 4FT.

PHYSICAL CHARACTERISTICS

074 62a PCR 230/F/A/Y/T Sealed. 07/25

WID 30 **RWS 90**

AERODROME AND APPROACH LIGHTING

RWY 07/25 PAPI(1) 3.0 DFG52FT

Left side. Manually activated 2HR PN. PAPI intensity manually controlled by ARO via CTAF (1) 126.5.

OTHER LIGHTING

RWY 07/25: Night emergency lights AVBL 2HR PN.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA MELBOURNE CENTRE 118.95

LOCAL TRAFFIC REGULATIONS

- RWY 07/25; all fixed wing ACFT must make MAX RAD turns at MNM speed at all RWY ends to avoid SFC damage. 2.
 - Day VMC OPS only.

CTAF 126.5

CHARTS RELATED TO THE AERODROME

WAC 3352.