


THE MONUMENT

ELEV 949

AVFAX CODE 4318



QLD  
214843S  
AD OPR Incitec Pivot Ltd (Southern Cross Fertilisers), L3, 19 Stanley Street,  
Townsville, QLD, 4810. Email:  
au\_ipi\_pho\_aviation\_aros@incitecpivotlimited.onmicrosoft.com. PH Site 07  
4747 0997: AD Manager 0408 297 265: AH 0438 603 224. ARO 0407 967 029.

UTC +10  
VAR 6 DEG E

YTMO  
CERT

REMARKS

Restricted OPS. PPR for all OPS.

HANDLING SERVICES AND FACILITIES

Ground handling and fuel by prior arrangement with ARO.

METEOROLOGICAL INFORMATION PROVIDED

1. TAF CAT C, METAR/SPECI.
2. AWIS PH 07 3564 3741 - Report faults to BoM.
3. AWIS FREQ 129.2 - Report faults to AD OPR.

PHYSICAL CHARACTERISTICS

14/32      140   62a   PCN 19/F/C/1.00 MPa/U

WID 30      RWS 150

AERODROME AND APPROACH LIGHTING

RWY 14/32      LIRL      PAL 119.65

RWY 14/32      PAPI(1)      PAL 119.65      3.0 DEG49FT      SDBY PWR AVBL

SDBY PWR AVBL

(1) Left hand side only.

RWY edge light spacing: 14/32: 90M.

OTHER LIGHTING

1. SDBY PWR switchover time: Manually activated - 1HR PN.
2. TWY LGT: Blue edge.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA      BRISBANE CENTRE      122.4 5500FT

FLIGHT PROCEDURES

All pilots are required to BCST their intentions inbound on company FREQ 129.45.

CTAF - AFRU 127.3

CHARTS RELATED TO THE AERODROME

1. WAC 3233.
2. Also refer to AIP Departure and Approach Procedures.