


**THE MONUMENT****ELEV 949****AVFAX CODE 4318**

QLD  
214843S 1395524E UTC +10 YTMO  
VAR 6 DEG E CERT  
AD OPR Incitec Pivot Ltd (Southern Cross Fertilisers), L3, 19 Stanley Street,  
Townsville, QLD, 4810. Email:  
au\_ipi\_pho\_aviation\_aros@incitecpivotlimited.onmicrosoft.com. PH Site 07  
4747 0997: AD Manager 0408 297 265: AH 0438 603 224. ARO 0407 967 029.

**REMARKS**

Restricted OPS. PPR for all OPS.

**HANDLING SERVICES AND FACILITIES**

Ground handling and fuel by prior arrangement with ARO.

**METEOROLOGICAL INFORMATION PROVIDED**

1. TAF CAT C, METAR/SPECI.
2. AWIS PH 07 3564 3741 - Report faults to BoM.
3. AWIS FREQ 129.2 - Report faults to AD OPR.

**PHYSICAL CHARACTERISTICS**

14/32 140 62a PCR 280/F/D/1.01 MPa/U WID 30 RWS 150

**AERODROME AND APPROACH LIGHTING**

RWY 14/32 LIRL PAL 119.65 SDBY PWR AVBL  
RWY 14/32 PAPI(1) PAL 119.65 3.0 DEG49FT SDBY PWR AVBL

(1) Left hand side only.

RWY edge light spacing: 14/32: 90M.

**OTHER LIGHTING**

1. SDBY PWR switchover time: Manually activated - 1HR PN.
2. TWY LGT: Blue edge.

**ATS AND AERODROME COMMUNICATION FACILITIES**

FIA BRISBANE CENTRE 122.4 5500FT

**FLIGHT PROCEDURES**

All pilots are required to BCST their intentions inbound on company FREQ 129.45.

**CTAF - AFRU** 127.3

**CHARTS RELATED TO THE AERODROME**

1. WAC 3233.
2. Also refer to AIP Departure and Approach Procedures.