


THANGOOL

ELEV 644

AVFAX CODE 4025



QLD242938S1503434EUTC +10VAR 10 DEG EYTNGCERT

AD OPR Banana Shire Council, PO Box 412, Biloela, QLD, 4715.

PH 4995 8241. ARO AH 0439 873 182. Council PH 07 4992 9500:

Fax 4992 3493. Website: www.banana.qld.gov.au.

REMARKS
AD Charges: refer to website for details.

HANDLING SERVICES AND FACILITIES

Fuel supplied by IOR Aviation Pty Ltd. AVGAS 100LL AVBL H24 Self-Serve Bowser - payment method via IOR Aviation tag for account holders or via the Fuel charge APP. JET A1 H24 Call out fee applies outside 0700 -1700 Local. PH: 0423 393 033.

AERODROME OBSTACLES

- Lit TWR:
- a. 820FT AMSL, BRG 010 MAG 0.8NM FM ARP. Infringes inner HZS.
 - b. 1,214FT AMSL, BRG 010 MAG 1.54NM FM ARP. Infringes inner HZS.

METEOROLOGICAL INFORMATION PROVIDED

- 1. TAF CAT D, METAR/SPECI.
- 2. AWIS PH 07 3564 3739 - Report faults to BoM.
- 3. AWIS FREQ 134.05 - Report faults to AD OPR.

PHYSICAL CHARACTERISTICS

10/28	102	50a	PCN 12/F/C/0.55 MPa/U Sealed	WID 30	RWS 90
14/32	130	26c	Unrated. Grey sand silt clay	WID 30	RWS 60

AERODROME AND APPROACH LIGHTING

RWY 10/28 LIRL AFRU+PAL 126.7 SDBY PWR AVBL
RWY 10/28 edge light spacing: 60M.

OTHER LIGHTING

- 1. SDBY PWR switchover time: APRX 5 SEC.
- 2. TWY LGT: Blue edge.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA BRISBANE CENTRE 119.55 Circuit Area

LOCAL TRAFFIC REGULATIONS

APN PRKG not AVBL when DH8C ACFT refuelling. Cone markers placed across front of ACFT.

FLIGHT PROCEDURES

Right hand CCTS required RWY 10.

CTAF - AFRU 126.7

CHARTS RELATED TO THE AERODROME

- 1. WAC 3340.
- 2. Also refer to AIP Departure and Approach Procedures.