WEDDERBURN

FLFV 850

FULL NOTAM SERVICE NOT AVBL UTC +10



NSW 341048S 1504832F AD OPR NSW Sport Aircraft Club Inc. PO Box 450. Campbelltown, NSW, 2560.

VAR 13 DEG E

UNCR

Email: nswsaccom@gmail.com, PH 0425 380 964.

REMARKS

OPS limited to a MTOW of 4,000KG or less, unless approved.

HANDLING SERVICES AND FACILITIES

Skvfuel AVGAS HJ self serve bowser activated by MC, V and Skyfuel carnets. PH 0418 862 100 or 0417 780 280. Oil AVBL for purchase with prior arrangement, CTC AD OPR.

AERODROME OBSTACLES

Trees surround the entire perimeter of the aerodrome.

PHYSICAL CHARACTERISTICS

17/35 32a Unrated, RWY LEN 980M. WID 15

RWY 35 significant down slope THR to mid RWY.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA SYDNEY CENTRE 124.55 On Ground

LOCAL TRAFFIC REGULATIONS

Circuit training by non-resident ACFT not permitted.

CTAF 122.55

NOISE ABATEMENT PROCEDURES

- Avoid flying over Appin Township.
- Circuit traffic should avoid flying over the populous areas to the north of the AD. 2

ADDITIONAL INFORMATION

- Windshear possible on both RWY in strong wind conditions especially from the west.
- 2. Model ACFT flying may take place HJ. OPR MNT 122.55 MHz.
- 3. Animal and bird hazard exists at all times, most prevalent at dawn and dusk.
- Caution: Drainage ditches between RWY and TWY. 4
- Caution: R555C (Holsworthy) 1NM east of the ARP.
- Grass strip ADJ to and west of the RWY, check primary wind sock for status.

CHARTS RELATED TO THE AERODROME

WAC 3456.