

Closed

Notification Report

Please be advised that the following ATS occurrence has been reported. Airservices encourages your feedback and any other information pertinent to this occurrence that you or your organisation is willing to share. This will facilitate the sharing of the lessons learned from the occurrence.

For additional information or to provide feedback on this occurrence, please contact safety.liaison@airservicesaustralia.com.

DISCLAIMER/TERMS OF RELEASE: Information provided in this report is copyright to Airservices and may not be reproduced or copied in any form or by any means or otherwise disclosed to any third party external to Airservices without the prior written consent of Airservices. Privacy of individual officers, organisations and/or operators is paramount, and where information identifying individual officers, organisations and/or operators is provided, it must remain secure and must not be released to third parties.

Report Number	Occurrence Type	Occurrence Date (UTC)	Occurrence Time (UTC)
ATS-0209994	Airspace Infringement	01/11/2024	04:48
Reporting Group/Branch(SDL)/Unit:	Occurrence Location Group/Branch(SDL)/Unit:		
Perth TCU	Perth TCU		

Summary

Airspace Infringement - KKQ

Detailed Description

An aircraft was observed to the east of YRTI tracking southbound.
The aircraft climbed into CTA-C to A035.
Perth Centre broadcast and established communications with aircraft as KKQ.

Airspace Category	Controlling Authority	ATS Service Provided
CTA	Airservices	Approach - surveillance
Location Code	Bearing (001 - 360)	Distance (nm)
YRTI	090	5
Latitude (dd:mm:ss)	Longitude (ddd:mm:ss)	
00:00:00 South	0000:00:00 East	

----- Principal Aircraft/Ground Vehicle -----

Civil Australian Registered

ACID/Callsign	Registration	ADEP	ADES
KKQ	KKQ	-	-

----- Other Aircraft/Ground Vehicle -----

-

ACID/Callsign	Registration	ADEP	ADES
-	-	-	-

----- Other Aircraft/Ground Vehicle -----

-

Closed

ACID/Callsign

Registration

ADEP

ADES

Airspace Infringement

Did the Airspace Infringement occur at: A critical location and at a point in time which interfered with the processing of traffic within controlled airspace?

No

From Airspace Category

Class G

If P, R or TRA Airspace - provide number

-

What activity was taking place in the P, R or TRA area?

-

Incursion Type

Vertical

Altitude Verified

Yes

Level where Aircraft Identified/Reported

A035

Lower level of CTA/CTR where aircraft first identified/reported

A020

Position and altitude where aircraft exited the area or was last observed

-

Step Radius (NM)

-

ATS Alerts

Not Applicable

Impact on ATS

NIL/Minor

Occurrence Review

Accountable Leader

47F

Occurrence Review Due Date

11/11/2024

Responsible Group/Branch(SDL)/Unit

Airservices Australia\Aerodromes\Perth Aerodrome & Airspace Services\Perth TCU

Does this occurrence require a detailed Occurrence Review?

No

A detailed Occurrence Review is required for all 'Airservices' attributable occurrences, or as requested. The Accountable Leader may nominate an Occurrence Review Officer/Delegate below, however retains responsibility for closure of the record. The scope and depth of analysis required is commensurate with the potential risk to ATM service delivery. The Occurrence Review must describe the risk characteristics of the occurrence, demonstrate an understanding of contributory factors and assess the performance of risk controls. All supporting evidence (e.g. Audio, Video replays, Screenshots, Journal entries, etc.) should be attached.

Closed

Occurrence Review Delegates

Person

Title

47F

Surname

47F

First Name

47F

Email Address

47F

Date of Birth

#####

Gender

#####

Employee Number

47F

Windows User Name

47F

Basis of Employment

Permanent F/T

Position Description

Air Traffic Controller

Position Number

47F

Position Status

Active

Supervisor

47F

Group/Branch(SDL)/Unit

Airservices Australia\Aerodromes\Perth Aerodrome & Airspace Services\Perth TCU

Group

Airservices Australia\Aerodromes

Location

Perth

Contact Address 1

Air Traffic Control Centre

Contact Address 2

Perth Airport

Post Code

-

Date Hired

29/07/1991

Termination Date

31/12/9999

Residential Details

Closed

Residential Address

#####

Residential Town Suburb

#####

Residential State

#####

Residential Postcode

#####

Registry

Role Types

<Undefined>

Group/Branch(SDL)/Unit Responsible Supervisor for

Group/Branch(SDL)/Unit

Perth TCU

Review Comments

No ATC attribution

Personnel Involved (Note: Visibility is restricted) - Enter all personnel involved, e.g. Controller/s, Shift Manager/s, etc.

-

Was Fatigue a consideration in this occurrence?

-

Review Completion

Review Complete?

Yes

Completed By

47F

Review Date

01/11/2024

Investigation

Investigation Required?

No

Investigator

-

Investigation Type

-

Investigation considerations & other comments

-

Closed

Occurrence Close

Close Off Date	Person Closing
11/11/2024	47F

Closing Comments
-

Close this Record?
Yes

Released by Airservices Australia under the Freedom of Information Act 1982

Closed

Notification Report

Please be advised that the following ATS occurrence has been reported. Airservices encourages your feedback and any other information pertinent to this occurrence that you or your organisation is willing to share. This will facilitate the sharing of the lessons learned from the occurrence.

For additional information or to provide feedback on this occurrence, please contact safety.liaison@airservicesaustralia.com.

DISCLAIMER/TERMS OF RELEASE: Information provided in this report is copyright to Airservices and may not be reproduced or copied in any form or by any means or otherwise disclosed to any third party external to Airservices without the prior written consent of Airservices. Privacy of individual officers, organisations and/or operators is paramount, and where information identifying individual officers, organisations and/or operators is provided, it must remain secure and must not be released to third parties.

Report Number	Occurrence Type	Occurrence Date (UTC)	Occurrence Time (UTC)
ATS-0212331	Malfunction of Aircraft System	01/02/2025	03:26

Reporting Group/Branch(SDL)/Unit:	Occurrence Location Group/Branch(SDL)/Unit:
Jandakot Tower	Jandakot Tower

Summary

Disabled aircraft

Detailed Description

PMW landing RWY24L advised a flat tyre and stopped on the RWY. Circuit aircraft resequenced for RWY24R and DRO advised. Aircraft cleared and RWY inspected before reopening.

Airspace Category	Controlling Authority	ATS Service Provided
CTR	Airservices	Aerodrome
Location Code	Bearing (001 - 360)	Distance (nm)
YPJT	-	-
Latitude (dd:mm:ss)	Longitude (ddd:mm:ss)	
00:00:00 South	0000:00:00 East	

----- **Principal Aircraft/Ground Vehicle** -----
Civil Australian Registered

ACID/Callsign	Registration	ADEP	ADES
PMW	PMW	-	-

----- **Other Aircraft/Ground Vehicle** -----
-

ACID/Callsign	Registration	ADEP	ADES
-	-	-	-

----- **Other Aircraft/Ground Vehicle** -----
-

Closed

ACID/Callsign

Registration

ADEP

ADES

Occurrence Review**Accountable Leader**

47F

Occurrence Review Due Date

-

Responsible Group/Branch(SDL)/Unit

Airservices Australia\Aerodromes\West Aerodrome Services\Jandakot Tower

Does this occurrence require a detailed Occurrence Review?

No

A detailed Occurrence Review is required for all 'Airservices' attributable occurrences, or as requested. The Accountable Leader may nominate an Occurrence Review Officer/Delegate below, however retains responsibility for closure of the record. The scope and depth of analysis required is commensurate with the potential risk to ATM service delivery. The Occurrence Review must describe the risk characteristics of the occurrence, demonstrate an understanding of contributory factors and assess the performance of risk controls. All supporting evidence (e.g. Audio, Video replays, Screenshots, Journal entries, etc.) should be attached.

Occurrence Review Delegates**Person****Title**

47F

Surname

47F

First Name

47F

Email Address

47F

Date of Birth

#####

Gender

#####

Employee Number

47F

Windows User Name

47F

Basis of Employment

Permanent F/T

Position Description

Air Traffic Controller

Position Number

47F

Position Status

Active

Supervisor

47F

Group/Branch(SDL)/Unit

Airservices Australia\Aerodromes\West Aerodrome Services\Jandakot Tower

Closed

Group

Airservices Australia\Aerodromes

Location

Perth

Contact Address 1

Tower Road

Contact Address 2

Melbourne Airport

Post Code

-

Date Hired

10/11/2014

Termination Date

31/12/9999

*Residential Details***Residential Address**

#####

Residential Town Suburb

#####

Residential State

#####

Residential Postcode

#####

*Registry***Role Types**

<Undefined>

Group/Branch(SDL)/Unit Responsible Supervisor for

-

Review Comments

-

Personnel Involved (Note: Visibility is restricted) - Enter all personnel involved, e.g. Controller/s, Shift Manager/s, etc.

-

Was Fatigue a consideration in this occurrence?

-

Review Completion

Closed

Review Complete?

-

Investigation

Investigation Required?

No

Investigator

-

Investigation Type

-

Investigation considerations & other comments

-

Occurrence Close

Close Off Date

-

Person Closing

47F

Closing Comments

-

Close this Record?

-

Re-Open Auto Archived/Closed

Re-Open Submitted Record

No

Person Re-Opening Record

-

Reason for Opening Record

-