

**AIP SUPPLEMENT
(SUP)**

AERONAUTICAL INFORMATION SERVICE,
AIRSERVICES AUSTRALIA, GPO BOX 367,
CANBERRA ACT 2601

AIRAC

H77/25

Effective: 202506111600 UTC

For **DISTRIBUTION** queries, contact:
Email: aim.editorial@airservicesaustralia.com

For **CONTENT** queries regarding this SUP, contact:
Email: docs.amend@airservicesaustralia.com

**AMENDMENTS TO DESIGNATED
AIRSPACE HANDBOOK (DAH)
EFFECTIVE 12 JUNE 2025**

1. INTRODUCTION

- 1.1 This SUP will cancel and replace SUP H36/25 on 12 June 2025.
- 1.2 The purpose of this SUP is to amend Section 22 (IFR WAYPOINTS) of the DAH effective 12 June 2025.

2. ACTION

- 2.1 Add the following new waypoints to DAH Section 22:

BOPNI	123052.2S	1311920.0E	EC2NG	355721.2S	1445107.2E
BT2ND	371806.9S	1434407.1E	EC2NH	361212.1S	1444548.4E
BT2NE	371534.7S	1435033.7E	EC2NI	355911.3S	1444523.4E
BT2NF	372528.1S	1434839.2E	EC2SA	362155.9S	1445156.1E
BT2NG	371932.7S	1435545.2E	EC2SB	362520.8S	1444613.5E
BT2NI	372031.4S	1434936.5E	EC2SC	362210.5S	1444018.4E
BT2SA	374340.3S	1435106.4E	EC2SF	361520.3S	1444554.4E
BT2SC	374213.8S	1433924.6E	EC2SH	360719.9S	1444539.0E
BT2SF	373619.1S	1434633.0E	EC2SI	362020.6S	1444603.9E
BT2SI	374115.7S	1434535.2E	ED2NA	342920.1S	1383324.6E
EC2ND	355735.8S	1443933.1E	ED2NC	343045.6S	1384454.6E
EC2NE	355411.1S	1444513.9E	ED2NF	343643.1S	1383757.1E
EC2NF	360411.6S	1444533.0E	ED2NH	344011.2S	1383201.4E

ED2NM	344134.4S	1383704.4E	NW2SM	345728.3S	1503132.7E
HB2EB	425831.0S	1474204.1E	NW2SN	350246.9S	1502105.5E
HB2EC	425941.5S	1473812.9E	NW2ST	345503.2S	1503342.5E
HB2EF	425334.0S	1473519.4E	PJ2ED	315422.2S	1160202.4E
HB2EH	424906.4S	1472916.0E	PJ2EF	320206.9S	1155850.8E
HB2EI	425541.3S	1473812.7E	PJ2EG	320201.2S	1160829.0E
HB2EM	425113.9S	1473208.9E	PJ2EH	320352.7S	1154556.1E
HB2WD	424354.1S	1471129.1E	PJ2EI	315911.7S	1160337.5E
HB2WF	424456.7S	1472339.3E	PJ2SF	320838.1S	1155826.3E
HB2WG	423652.2S	1472146.2E	PJ2SH	320410.8S	1154510.9E
HB2WH	425119.8S	1473216.6E	PJ2SI	321056.2S	1160340.2E
HB2WI	424057.6S	1471817.8E	PJ2SK	321314.1S	1160854.4E
HB2WM	424912.2S	1472924.0E	PJ2SL	321554.4S	1160255.1E
MUDMI	123414.9S	1311241.7E	PJ2WA	321404.6S	1154717.1E
NW2EE	345356.2S	1504504.3E	PJ2WB	320732.9S	1154148.8E
NW2EF	345717.3S	1503813.1E	PJ2WF	320829.1S	1154823.0E
NW2EG	345753.2S	1504755.5E	PJ2WH	320932.6S	1155257.5E
NW2EI	345735.3S	1504304.3E	PJ2WI	321048.8S	1154432.8E
NW2EJ	350126.7S	1504423.4E	PJ2WM	320609.3S	1155213.0E
NW2EM	345659.0S	1503322.0E	PQ2ND	311140.2S	1525230.6E
NW2ET	345644.9S	1502939.4E	PQ2NE	311240.2S	1530040.8E
NW2NA	344631.7S	1503808.4E	PQ2NF	312122.7S	1525453.7E
NW2NC	344716.3S	1504338.3E	PQ2NG	311752.1S	1530332.6E
NW2ND	345147.2S	1504440.5E	PQ2NH	312820.5S	1525015.2E
NW2NF	345300.3S	1503650.9E	PQ2NI	311701.5S	1525747.4E
NW2NI	345008.3S	1504014.7E	PQ2SA	313906.4S	1524924.0E
NW2NM	345552.2S	1503326.9E	PQ2SB	313937.7S	1524242.3E
NW2NT	345801.0S	1503053.8E	PQ2SC	313404.7S	1523732.5E
NW2SF	350041.7S	1502839.3E	PQ2SF	313055.7S	1524831.6E
NW2SI	350355.1S	1502545.8E	PQ2SH	312358.0S	1525310.3E
NW2SK	350715.3S	1502827.4E	PQ2SI	313516.7S	1524537.1E
NW2SL	350708.3S	1502252.0E	PW3SB	312132.2S	1365245.3E

PW3SE	312420.5S	1364654.3E	SV2EH	123510.0S	1420138.6E
PW3SF	311422.2S	1364805.4E	SV2EI	124304.7S	1421442.3E
PW3SG	312034.9S	1364150.2E	SV2WD	123446.2S	1415150.8E
PW3SH	310623.6S	1364902.1E	SV2WE	122901.0S	1415130.7E
PW3SI	311921.3S	1364729.9E	SV2WF	123417.9S	1420012.7E
SHEPO	122755.8S	1313836.9E	SV2WG	122644.3S	1415653.9E
SV2EA	123957.6S	1421843.0E	SV2WH	123934.5S	1420855.0E
SV2EB	124542.7S	1421903.7E	SV2WI	123139.5S	1415551.6E
SV2EC	124759.9S	1421340.4E	VIMIN	122809.6S	1313110.8E
SV2EF	124026.5S	1421021.0E			

2.2 Delete the following waypoints from DAH Section 22:

BIDSA	BSGEM	ECHSH	PJTED	PQQNG	SNWEH
BLZND	BSGWD	ECHSI	PJTEF	PQQNH	SNWEI
BLZNE	BSGWE	EDNNA	PJTEG	PQQNI	SNWEJ
BLZNF	BSGWF	EDNNC	PJTEH	PQQSA	SNWEM
BLZNG	BSGWG	EDNNF	PJTEI	PQQSB	SNWNA
BLZNH	BSGWH	EDNNI	PJTSE	PQQSC	SNWNC
BLZNI	BSGWI	EDNNM	PJTSH	PQQSF	SNWND
BLZNM	BSGWM	HBTEB	PJTSE	PQQSH	SNWNF
BLZSA	DUGAM	HBTEC	PJTSE	PQQSI	SNWNH
BLZSC	ECHND	HBTEF	PJTSL	PW2SB	SNWNI
BLZSF	ECHNE	HBTEH	PJTWA	PW2SE	SNWNM
BLZSH	ECHNF	HBTEI	PJTWB	PW2SF	SNWSF
BLZSI	ECHNG	HBTEM	PJTWF	PW2SH	SNWSH
BLZSM	ECHNH	HBZWD	PJTWH	PW2SI	SNWSI
BSGEA	ECHNI	HBZWF	PJTWI	PW2SJ	SNWSK
BSGEB	ECHSA	HBZWG	PJTWM	PW2SM	SNWSL
BSGEC	ECHSB	HBZWH	PQQND	SNWEE	SNWSM
BSGEF	ECHSC	HBZWI	PQQNE	SNWEF	SNWSN
BSGEI	ECHSF	HBZWM	PQQNF	SNWEG	

3. CANCELLATION

- 3.1 This SUP will be cancelled when it is incorporated into AIP DAH, expected 27 November 2025.

4. DISTRIBUTION

- 4.1 Airservices Australia website only.