

USE QNH NDB-Y RWY 36
COOMA-SNOWY MOUNTAINS, NSW (YCOM)

NDB	GS (KNOTS)	60	70	80	90	100	110	120	130							
to MAPt	TIME (MIN:SEC)	2:45	2:22	2:04	1:50	1:39	1:30	1:23	1:17							

MISSED APPROACH:
 TRACK 001°
 PASSING 4600ft TURN LEFT,
 TRACK TO NDB.
 CLIMB TO 5700ft.

CAUTION: AERODROME 2.7 NM
 NORTH OF THE NDB.

The diagram illustrates a missed approach procedure starting from a point labeled "MAPt #" (marked with an asterisk). The initial track is 001°. The pilot passes 4600 ft, turns left, and climbs to 5700 ft. From 5700 ft, the track changes to 157°, passing 4800 ft, where it becomes 001° again. The final destination is "COM NDB", indicated by a triangle symbol. A shaded cone extends from the NDB towards the MAPt. Other labels include "THR 36 ELEV 3087".

CATEGORY	A	B	D	* 1. NO CIRCLING WEST OF RWY 18 / 36.
S-I NDB	3940	(853-4.2)	NOT APPLICABLE	#2. GRADIENT AFTER FAF 6.4% (390FT/NM).
				3. AWIS (PHONE) 02 9353 6414
CIRCLING *	4060	(954-2.4)		4. COLOUR: SEE SPEC NOTICES.
ALTERNATE		(1454-4.4)		

COMNB02-180