

TRANSITIONS:

WAGGA: From WG VOR or NDB to POLLI:

(WG) • Track 110° to POLLI

• Then follow ARRIVAL instructions

KACEY: From KACEY to POLLI:

Track 090° to POLLI

• Then follow ARRIVAL instructions

ARRAN: From ARRAN to POLLI:

Track 071° to POLLI

Then follow ARRIVAL instructions

EBONY: From EBONY to POLLI:

• Track 058° to POLLI

Then follow ARRIVAL instructions

SCBSR07-176

ARRIVAL: POLLI NINE

RWY 35 X-RAY

Cross POLLI AT or BLW FL170

- From POLLI track 058° to BIXAV Cross BIXAV AT or ABV 9000ft
- Track 058° TO GOMAN
- Cross GOMAN AT or ABV 7600ft
- Turn LEFT, track 057° TO HONEY Cross HONEY AT or ABV 7000ft
- Turn LEFT, track 037° TO ANREP
 Turn LEFT, track 033° TO KALKA
- Turn LEFT, track 033° TO KALKA Cross KALKA AT or ABV 6000ft
- Track via RNP X RWY 35 (AR)

COMMUNICATIONS FAILURE: PROCEDURE IN IMC

- Squawk 7600, comply with vertical navigation requirements, but not below MSA.
- Track via the latest STAR clearance to the nominated runway, then fly the most suitable approach in accordance with ERSA EMERG Section 1.5.

Changes: REVISED PROC.

