

BRUNY ISLAND

ELEV 26

FULL NOTAM SERVICE NOT AVBL

TAS

UTC +10

YBYI

431406S

1472247E

VAR 16 DEG E

UNCR

AD OPR Bruny Island Aviation Trust, 3959 Bruny Island Main Road, Bruny Island, TAS, 7150. Email: info@brunyisland.com. Mobile 0427 931 271. Website: www.brunyisland.com.

REMARKS

1. AD Charges: by donation.
2. PH AD OPR prior to ARR for RWY conditions.

PHYSICAL CHARACTERISTICS

14/32	21c	Unrated. Gravel. RWY LEN 650M. Slope level. WID 10	RWS 25
-------	-----	--	--------

ATS AND AERODROME COMMUNICATION FACILITIES

FIA	HOBART CENTRE	(2)	125.55
-----	---------------	-----	--------

UNICOM	BRUNY ISLAND UNICOM	126.7 (1)
--------	---------------------	-----------

- (1) CS "Bruny UNICOM" when AVBL.
- (2) Outside HB TWR and APP HR ML CENTRE.

LOCAL TRAFFIC REGULATIONS

Confirm PRKG SFC conditions following rain.

CTAF 126.7

FLIGHT PROCEDURES

Right hand CCTS on RWY 14 due to terrain.

ADDITIONAL INFORMATION

1. Trees on both APCH paths with high GND near the RWY 14 APCH.
2. Caution: Turbulence.
3. Splay areas below ALA recommended MNM due to hangar and perimeter trees.
4. Wildlife hazard exists.

CHARTS RELATED TO THE AERODROME

WAC 3556.