CASINO AVEAX CODE 2027

FLFV 86 FULL NOTAM SERVICE NOT AVBL

UTC +10

NSW 285258S 1530401E VAR 11 DEG E **UNCR**

AD OPR Richmond Valley Council, Locked Bag 10, Casino, NSW, 2470, PH 02 6660 0300 H24. Fax 02 6660 1300. Website: www.richmondvallev.nsw.gov.au.



REMARKS

AD charges: all ACFT - see website.

HANDLING SERVICES AND FACILITIES

World Fuel Services (WFS): H24 AVGAS bowser WFS card swipe and credit card (via smart phone APP) PH: 0422 441 277 (H24) or email: lismorejeta1@gmail.com.

METEOROLOGICAL INFORMATION PROVIDED

- 1. METAR/SPECI.
- 2. AWIS - PH 02 9353 6409 - Report faults to BoM.

PHYSICAL CHARACTERISTICS

10/28 094 36a PCN 14 /F /D /580 (84PSI) /T Grooved **WID 30 RWS 150**

ATS AND AERODROME COMMUNICATION FACILITIES FIA **BRISBANE CENTRE** 120.3 On ground

LOCAL TRAFFIC REGULATIONS

- 1 All pilots are required to BCST their intentions on the CTAF before OPR on RWY.
- 2. Due to the possibility of ACFT at opposite ends of the RWY not being visible to each other, in NIL-wind COND, OPS should be confined to RWY 10.
- ACFT parking AVBL on sealed area at W end or RWY adjacent to BDRY fence.

CTAF 132.45

ADDITIONAL INFORMATION

- Fruit bat hazard may exist in circuit area. Main activity from last light to 1.5HR after last light between December and end of February.
- Powered paragliders OPR from AD. 2.

CHARTS RELATED TO THE AERODROME

WAC 3357.