

CRESSY

ELEV 420


FULL NOTAM SERVICE NOT AVBL

VIC
380224S
AD OPR CSS Investments, 175 Aerodrome Road, Cressy, VIC, 3320. Email:
cressyaerodrome@inet.net.au. PH 0481 327 587.

UTC +10
VAR 11 DEG E

YCRE
UNCR

1433911E



REMARKS
PPR.

HANDLING SERVICES AND FACILITIES
No fuel AVBL.

PASSENGER FACILITIES
WC/RF/HC/AC.

AERODROME OBSTACLES
1. Powerlines on the approach to RWY 33.
2. Unlit TWY 355 DEG MAG 0.8NM FM ARP.

01/19	36c	Unrated. Grass. RWY LEN 1,100M	WID 50
15/33	30c	Unrated. Grass. RWY LEN 900M	WID 50

AERODROME AND APPROACH LIGHTING
RWY 01/19 PTBL(1) BY PRIOR ARRANGEMENT

(1) 30MIN PN.

ATS AND AERODROME COMMUNICATION FACILITIES
FIA MELBOURNE CENTRE 126.8

FLIGHT PROCEDURES
1. Right hand circuits when operating on RWY 01 and 33.
2. Pilots are encouraged to avoid overflying Cressy township and properties to the S.
3. Aircraft approaching from NW or W to track via Lake Rosine and when approaching from S track via the eastern shore of Lake Weering.

CTAF 126.7

ADDITIONAL INFORMATION
Railway tracks are close to the threshold of RWY 15 and 19.

CHARTS RELATED TO THE AERODROME
WAC 3469.