

CLARE VALLEY

Diagram showing runway 35 with a bearing of 160° 8NM to Clare.

ELEV 1120

FULL NOTAM SERVICE NOT AVBL

SA

334230S

1383500E

UTC +9:30

VAR 8 DEG E

YCVA

UNCR

AD OPR Clare Valley Flying Group Inc, PO Box 1502, Clare, SA, 5453. Email: cvfg@clarevalleyaerodrome.com.au. PH Chairman - 0418 891 205. Mobile Secretary - 0407 829 584. Website: www.clarevalleyaerodrome.com.au.

REMARKS

Donations for use appreciated.

HANDLING SERVICES AND FACILITIES

AVGAS AVBL H24. Use Compac Pay mobile APP. Organisation code for site: 389KP4  
PH: 0412 602 447.

PASSENGER FACILITIES

LG/WC/TX/RF. Courtesy car AVBL at AD. Further information and bookings AVBL online: www.clarevalleydownwind.com.au.

PHYSICAL CHARACTERISTICS

|       |     |                                  |        |        |
|-------|-----|----------------------------------|--------|--------|
| 09/27 | 20c | Unrated. Grass. RWY LEN 600M.    | WID 30 |        |
| 17/35 | 41a | Unrated. Sealed. RWY LEN 1,250M. | WID 18 | RWS 22 |

AERODROME AND APPROACH LIGHTING

RWY 17/35      LIRL      PAL 120.05

ATS AND AERODROME COMMUNICATION FACILITIES

FIA      MELBOURNE CENTRE      118.95

CTAF 126.7

NOISE ABATEMENT PROCEDURES

- All ACFT to avoid overflying Bungaree Station 1.3NM SW THR RWY 35 BLW 2,300FT AMSL.
- ACFT to track close downwind when using RWY 35 to avoid Bungaree Station.
- TRNG ACFT inbound from S to track via overhead Clare township not below 2,600FT AMSL.

ADDITIONAL INFORMATION

Kangaroo and deer hazard may exist.

CHARTS RELATED TO THE AERODROME

WAC 3458, 3459.

Information may be continued on the next page: PTO