

02

02

02

33

VIC

380849S

1441021E

AD OPR Craig Taberner, 470 Pollocksford Rd, Gnarwarre, VIC, 3221. Email: ctaberne@ford.com. PH 0439 154 202 (H24).

FULL NOTAM SERVICE NOT AVBL

UTC +10

VAR 11 DEG E

ELEV 260

YGBF

UNCR

REMARKS

PPR.

PHYSICAL CHARACTERISTICS

02/20

28c

Unrated. Grass. RWY LEN 850M

WID 15

15/33

28c

Unrated. Grass. RWY LEN 850M

WID 15

ATS AND AERODROME COMMUNICATION FACILITIES

FIA

MELBOURNE CENTRE

134.325

FLIGHT PROCEDURES

1.

Right hand circuits for RWY 02 and RWY 33.

2.

No landing on RWY 02 due to rising terrain to south.

CTAF 119.0

ADDITIONAL INFORMATION

Pilots should consider noise impacts and avoid overflying residential buildings.

CHARTS RELATED TO THE AERODROME

WAC 3469, 3470.