


INVERELL

ELEV 2669

AVFAX CODE 2049



NSW
295318S
AD OPR Inverell Shire Council, PO Box 138, Inverell, NSW, 2360. PH 02 6728 8288. ARO 0428 477745. PH AH 0428 477 745.

1510839E
VAR 11 DEG E

UTC +10
YIVL
CERT

REMARKS

AD Charges: Airline ACFT.

HANDLING SERVICES AND FACILITIES

Nil fuel AVBL.

METEOROLOGICAL INFORMATION PROVIDED

1. AWIS PH 02 6723 1198 - report faults to AD OPR
2. AWIS FREQ 122.425 (requires one pulse to activate) - report faults to AD OPR.

PHYSICAL CHARACTERISTICS

04/22 039 23c Unrated. Grassed granite soil

16/34 159 69c PCN 10/F/B/0.58 MPa/U Sealed

WID 18 RWS 60

WID 30 RWS 150

AERODROME AND APPROACH LIGHTING

RWY 16/34 LIRL AFRU+PAL 126.7

RWY 16/34 PAPI AFRU+PAL 126.7 3.0 DEG41FT

RWY edge light spacing: 16/34: 60M.

SDBY PWR AVBL

SDBY PWR AVBL

OTHER LIGHTING

1. Secondary PWR switchover time: 15 SEC.
2. TWY LGT: Blue edge on TWY A.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA BRISBANE CENTRE

127.1 Circuit Area

RADIO NAVIGATION AND LANDING AIDS

NDB IVL 260 295304.9S 1510823.9E Range 40 (HN 40)

LOCAL TRAFFIC REGULATIONS

Due to RWY levels, ACFT may not be sighted on opposite ends of the RWY.

CTAF - AFRU 126.7

CHARTS RELATED TO THE AERODROME

1. WAC 3357.
2. Also refer to AIP Departure and Approach Procedures.