


STREAKY BAY

ELEV 69

AVFAX CODE 5309



SA
325009S
AD OPR District Council of Streaky Bay, PO Box 179, Streaky Bay, SA,
5680. Email: info@streakybay.sa.gov.au. PH 08 8626 1001. PH AH 0459
874 559.

UTC +9:30
1341734E
VAR 6 DEG E

YKBY
CERT

REMARKS

- 1. AD Charges: All ACFT.
- 2. AD AVBL for public use.

PASSENGER FACILITIES

WC

APRONS AND TAXIWAYS

- 1. TWY A 10.5M sealed.
- 2. TWY B 15M unrated gravel. MTOW 5,700KG.

AERODROME OBSTACLES

RWY 13/31 transitional SFC N side infringed by fence up to 3.5FT.

PHYSICAL CHARACTERISTICS

05/23	046	26c	Unrated. Gravel	WID 18	RWS 90
13/31	124	44a	Unrated.	WID 18	RWS 90

AERODROME AND APPROACH LIGHTING

RWY 13/31 LIRL PAL+AA 120.6

RWY 13/31 edge light spacing: 60M.

SDBY PWR AVBL

OTHER LIGHTING

- 1. Secondary PWR switchover time: 30 SEC.
- 2. TWY LGT: Blue edge.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA MELBOURNE CENTRE 123.5 Circuit Area

CTAF 126.7

ADDITIONAL INFORMATION

- 1. Animal hazard (kangaroo) exists.
- 2. Caution: ACFT at opposite ends of RWY 13/31 may not be visible to each other.

CHARTS RELATED TO THE AERODROME

- 1. WAC 3459.
- 2. Also refer to AIP Departure and Approach Procedures.