#### BELYANDO/LABONA

**FLFV 805** 

# **FULL NOTAM SERVICE NOT AVBL**



OI D UTC +10 220016S 1462150E VAR 8 DEG E **UNCR** 

AD OPR Adani Mining Ptv Ltd. Level 9, 120 Edward St. Brisbane, QLD, 4000. Email: rod.ward@sodexo.com; adani.aro@bravus.com.au, PH Rod Ward 0431 559 986 H24, ARO 0409 531 338 H24,

## REMARKS

Private AD. PPR for all OPS. Email AD OPR.

# HANDLING SERVICES AND FACILITIES

IOR JET A1 AVBL - IOR account required.

## PASSENGER FACILITIES

I G/WC.

### AFRODROME OBSTACLES

Lit mast 98FT AGL BRG 161 DEG MAG 1.52NM FM ARP.

### PHYSICAL CHARACTERISTICS

18/36 Unrated. RWY LEN 1,105M. Slope 0.89% **RWS 80** 36a **WID 18** 

down to N.

## OTHER LIGHTING

Solar RWY LGT AVBL for emergency services only.

## ATS AND AERODROME COMMUNICATION FACILITIES

FIA BRISBANE CENTRE 128.55 UNICOM **BELYANDO-LABONA** 126.7 (1) UNICOM

CS "Safety 1".

## (1) LOCAL TRAFFIC REGULATIONS

PRKG bavs unmarked. Follow ARO directions.

Make a 'Rolling' call when lined up and prior to take-off due to line of sight limitations. 2.

#### **CTAF** 126.7

#### ADDITIONAL INFORMATION

Bird and wildlife hazard exists:

- Galahs and black kites in VCY of AD.
- b. Rabbits may be on airfield.
- c. Increased bird activity early morning and late afternoon.
- d. ARO will advise inbound aircraft via CTAF for increased bird activity.

## CHARTS RELATED TO THE AERODROME

WAC 3234.