

8L

070° 15NM
Belyando

36

⊕

✈

QLD

220016S

1462150E

AD OPR Adani Mining Pty Ltd, Level 9, 120 Edward St, Brisbane, QLD, 4000.

Email: rod.ward@sodexo.com: adani.aro@bravus.com.au.

PH Rod Ward 0431 559 986 H24. ARO 0409 531 338 H24.

ELEV 805

FULL NOTAM SERVICE NOT AVBL

UTC +10

VAR 8 DEG E

YLBA

UNCR

REMARKS

Private AD. PPR for all OPS. Email AD OPR.

HANDLING SERVICES AND FACILITIES

IOR JET A1 AVBL - IOR account required.

PASSENGER FACILITIES

LG/WC.

AERODROME OBSTACLES

Lit mast 98FT AGL BRG 161 DEG MAG 1.52NM FM ARP.

PHYSICAL CHARACTERISTICS

18/36

36a

Unrated. RWY LEN 1,105M. Slope 0.89% down to N.

WID 18

RWS 80

OTHER LIGHTING

Solar RWY LGT AVBL for emergency services only.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA

BRISBANE CENTRE

128.55

UNICOM

BELYANDO-LABONA

126.7 (1)

UNICOM

(1)

CS "Safety 1".

LOCAL TRAFFIC REGULATIONS

1.

PRKG bays unmarked. Follow ARO directions.

2.

Make a 'Rolling' call when lined up and prior to take-off due to line of sight limitations.

FLIGHT PROCEDURES

Right hand CCTS RQ when OPR on RWY 18.

CTAF 126.7

ADDITIONAL INFORMATION

Bird and wildlife hazard exists:

a.

Galahs and black kites in VCY of AD.

b.

Rabbits may be on airfield.

c.

Increased bird activity early morning and late afternoon.

d.

ARO will advise inbound aircraft via CTAF for increased bird activity.

CHARTS RELATED TO THE AERODROME

WAC 3234.

Information may be continued on the next page: PTO