


DJARINDJIN/LOMBADINA
AVFAX CODE 6917
WA
163055S
AD OPR Djarindjin Airport Pty Ltd, PO Box 920, Broome, WA, 6725. Email:
supervisors@djairindjin.org.au. PH 08 9192 4940. AD MGR/ARO: 0418 791 019. AD MGR: 0419
837 572. Website: www.djarindjinairport.com.au.

ELEV 155
UTC +8
VAR 1 DEG E
YLBD
CERT



REMARKS

1. PPR HN.

2. AD charges: all ACFT.

3. Airside gate access codes AVBL FM Duty Supervisor (phone ARO).

PASSENGER FACILITIES

WC/PT/LG/AC/RF

SURFACE MOVEMENT GUIDANCE

Drains located airside are not marked.

METEOROLOGICAL INFORMATION PROVIDED

1. TAF CAT B, METAR/SPECI.

2. AWIS FREQ 128.60 (requires one two-second pulse to activate) - Report faults to AD OPR.

PHYSICAL CHARACTERISTICS

10/28 104 39a Unrated.

WID 18 RWS 80

AERODROME AND APPROACH LIGHTING

RWY 10/28 LIRL PAL 119.65
RWY 10/28 PTBL(1)

SDBY PWR AVBL
BY PRIOR
ARRANGEMENT

- (1) EMERG only. 45MIN PN.

RWY 10/28 edge light spacing: 60M.

OTHER LIGHTING

Secondary PWR switchover time: 15SEC.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA BRISBANE CENTRE 122.1

LOCAL TRAFFIC REGULATIONS

RWS not MNTN for ACFT OPS.

CTAF 127.2

CHARTS RELATED TO THE AERODROME

1. WAC 3223.

2. Also refer to AIP Departure and Approach Procedures.