


MARYBOROUGH (VIC)**ELEV 766****FULL NOTAM SERVICE NOT AVBL**

VIC
370159S 1434232E UTC +10 YMBU
VAR 11 DEG E UNCR

AD OPR Central Goldfields Shire Council, 22 Nolan Street, Maryborough,
3465. Email: mail@cgoldshire.vic.gov.au. PH 03 5461 0610. Fax 03 5461
0666.

REMARKS

AD not AVBL to ACFT ABV 5,700KG MTOW.

PASSENGER FACILITIES

WC/TX (03 5461 1633)/RF/LG (Access Code C19; turn knob clockwise).

AERODROME OBSTACLES

Trees in the vicinity of runway may impact the approach or departure of
aircraft.

PHYSICAL CHARACTERISTICS

06/24	21	5700 kg/0.45 MPa Unrated. Gravel	WID 30	RWS 90
17/35	34a/b	5700 kg/0.65 MPa Unrated. Sealed	WID 30	RWS 90

AERODROME AND APPROACH LIGHTING

RWY 17/35 LIRL AFRU+PAL 119.1

RWY edge light spacing: 17/35: 87M.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA MELBOURNE CENTRE 126.8 Circuit Area

LOCAL TRAFFIC REGULATIONS

1. Circuit training not permitted 2200-0700 Local.
2. ACFT on different RWY may not be visible to each other.
3. HLS FATO/TKOF 35M diameter. HLS MTOW unlimited.
4. Radios to be carried and used.

FLIGHT PROCEDURES

Right hand circuit RQ when OPR on RWY 17 and 24.

CTAF - AFRU 119.1

ADDITIONAL INFORMATION

1. Bird hazard exists.
2. Kangaroos may be on RWY - pilots should conduct a flyover before landing.

CHARTS RELATED TO THE AERODROME

WAC 3469.