

MURRIN MURRIN

ELEV 1535

AVFAX CODE 6107



WA
284219S
AD OPR Minara Resources Pty Ltd, Murrin Murrin Operations, PO Box
Z5523, Perth, WA, 6831. Email: siteservices.supt.coord@glencore.com.au.
PH 08 9088 5957 (BH). ARO 0408 941 791. Mobile 0408 657 461 (AH).

1215326E
UTC +8
VAR 1 DEG E

YMMI
CERT

REMARKS
Restricted Operations. PPR from AD Manager/AROs.

HANDLING SERVICES AND FACILITIES
Nil fuel AVBL.

PASSENGER FACILITIES

LG/WC/PT

AERODROME OBSTACLES

- 1. Illuminated WDI 209M N of RWY 03 start of TORA 100M E of RWY CL infringes transitional SFC by 10FT.
- 2. Transient E190 ACFT tail 1,567FT AMSL BRG 209 DEG MAG 885M FM ARP. Infringes TNS by 11FT.

PHYSICAL CHARACTERISTICS

03/21 034 66a Unrated. Sealed.

WID 30 RWS 150

AERODROME AND APPROACH LIGHTING

RWY 03/21 LIRL

RWY 03/21 PAPI(1)

3.0 DEG50FT

SDBY PWR AVBL

SDBY PWR AVBL

- (1) Left side.
- 1. RWY edge light spacing: 03/21: nominal 90M.
- 2. Lighting manually activated. 30MIN PN.

OTHER LIGHTING

- 1. Standby PWR derived from generator. Switchover time: 10 SEC.
- 2. TWY LGT: Blue edge.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA MELBOURNE CENTRE

118.4 Circuit Area

LOCAL TRAFFIC REGULATIONS

- 1. ACFT ABV 5,7000KG to use MAX RAD MNM speed turns at RWY ends only.
- 2. Second ACFT PRKG AVBL on RWY adjacent to TWY entrance. NOTAM will be issued advising RWY not AVBL. CTC ARO.

CTAF - AFRU 126.8

AFRU signal not AVBL on ground Laverton, Murrin Murrin or Sunrise Dam. AFRU located at Leonora.

ADDITIONAL INFORMATION

Mine site 2.5NM, BRG 179DEG M.

CHARTS RELATED TO THE AERODROME

- 1. WAC 3352.
- 2. Also refer to AIP Departure and Approach Procedures.