RIDDELL

VIC

FIA

372848S

1444306E

UTC +10

FULL NOTAM SERVICE NOT AVBL YRID

UNCR

ELEV 1150

VAR 11 DEG E AD OPR Riddell Airfield Ptv Ltd. PO Box 164. Riddell's Creek. VIC. 3431. PH 0402 042 015: 0417 056 582.

REMARKS

- 1. PPR.
- 2. Charges apply.

ATS AND AERODROME COMMUNICATION FACILITIES

135.7 On Ground

LOCAL TRAFFIC REGULATIONS

MEI BOURNE CENTRE

No precautionary search or engine failure training permitted.

FLIGHT PROCEDURES

- 1. No straight in approaches permitted for any RWY.
- 2. Subject to operational requirements, pilots are to adopt appropriate PWR settings for TKOF, CCTS and landings to minimise noise levels.
- A limit of six consecutive CCTS for any ACFT within any three hour period. A limit of three 3. ACFT within the circuit at any one time.
- 4. All CCTS to the east.

CTAF 121.6

ADDITIONAL INFORMATION

- Animal hazard and windshear may exist. 1.
- PH to confirm grass RWY serviceability. 2.

CHARTS RELATED TO THE AERODROME

WAC 3469, 3470.