

RAYWOOD

81

▲

280° 2.5NM

Raywood

▲

60

▲

36

▲

27

▲

VIC

363230S

1441428E

AD OPR Bendigo Gliding Club Inc, PO Box 846, Bendigo, VIC, 3552. Email: secretary@bendigogliding.org.au. PH 0492 923 215. Website: www.bendigogliding.org.au.

ELEV 450

FULL NOTAM SERVICE NOT AVBL

UTC +10

YRYW

VAR 11 DEG E

UNCR

REMARKS

1. PPR.

2. Aerotow and winch launching OPS.

3. Gliding OPS HJ DLY.

HANDLING SERVICES AND FACILITIES

Nil fuel AVBL.

PHYSICAL CHARACTERISTICS

09/27

30c

Unrated. Grass. RWY LEN 900M.

WID 90

18/36

43c

Unrated. Grass. RWY LEN 1,300M.

WID 90

ATS AND AERODROME COMMUNICATION FACILITIES

FIA

MELBOURNE CENTRE

126.8

FLIGHT PROCEDURES

1. Gliders and tugs may fly contra CCTS.

2. Gliders and tugs normally operate inside and below standard 1000FT circuit.

3. RWY 09 not available if gliders launching on RWY 36.

4. RWY 36 not available if gliders launching on RWY 09.

CTAF 119.3

CHARTS RELATED TO THE AERODROME

WAC 3469, 3470.

Information may be continued on the next page: PTO