

CAROSUE DAM

AVFAX CODE 6117

WA

301025S

1221920E

AD OPR Northern Star (Carosue Dam) Pty Ltd, Level 1, 388 Hay Street, Subiaco, WA, 6008. Email: aerodromecarosuedam@nsr ltd.com. PH 08 6188 2100. ARO 08 6229 9014. ARO AH 0477 516 011.


ELEV 1291

UTC +8

VAR 1 DEG E

YSCD

CERT



REMARKS

- 1. PPR from AD OPR.
- 2. Parking by prior arrangement with AD OPR.

HANDLING SERVICES AND FACILITIES

Nil fuel AVBL.

PASSENGER FACILITIES

Passenger terminal/WC.

PHYSICAL CHARACTERISTICS

06/24	061	66a	PCR 250/F/B/Y/T Sealed	WID 30	RWS 150
-------	-----	-----	------------------------	--------	---------

AERODROME AND APPROACH LIGHTING

RWY 06/24	PAPI(2)	3.0 DEG48.5FT	BY PRIOR ARRANGEMENT
RWY 06/24	PTBL(1)		BY PRIOR ARRANGEMENT

- (1) EMERG lighting AVBL with 120 MIN PN to ARO.
- (2) Left side only. Manual activation of PAPI AVBL with 30MIN PN. HJ only.

OTHER LIGHTING

- 1. RWY edge light spacing: 06/24: 87M (PTBL).
- 2. No mains PWR AVBL - PAPI PWR supplied by generators.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA	MELBOURNE CENTRE	125.75
-----	------------------	--------

LOCAL TRAFFIC REGULATIONS

- 1. All ACFT to follow APN markings.
- 2. All fixed wing ACFT must make MAX RAD turns at MNM speed at all RWY ends to avoid SFC damage.
- 3. All fixed wing ACFT to use idle power for movements on the APN with the exception of breakaway thrust to initiate taxi. ACFT that cannot comply with this restriction must advise the AD OPR prior to departure.
- 4. Day OPS only EXC for EMERG.

CTAF - AFRU 126.7

CHARTS RELATED TO THE AERODROME

- 1. WAC 3352.
- 2. Also refer to AIP Departure and Approach Procedures.