FAC YTHN - 1 ELEV 1704

THUNDERBOX AVFAX CODE 6116

WA UTC +8 280914S 1205621E VAR 1 DEG E AD OPR Northern Star (Thunderbox), Locked Bag 2, Leonora, WA, 6438. Email: tboaerodrome@nsrltd.com. PH 08 6228 9500. AD Manager PH 0428 666 673. Email: alabrown@nsrltd.com. ARO H24 0483 188 518. Website: www.nsrltd.com.

> 319° 19.1NM Leinster 1900 ⊕ ↓

REMARKS

1. PPR from AD OPR.

2. AD AVBL HJ only EXC for EMERG.

HANDLING SERVICES AND FACILITIES

Ground handling and fuel (JET A1) by prior arrangement with AD OPR.

PASSENGER FACILITIES

WC.

AERODROME OBSTACLES

- 1. Fence parallel to RWY CL, 53M S of RWY CL, infringes transitional SFC by 2FT.
- 2. Mine site BRG 119 DEG MAG 4.5NM FM ARP.
- Unmarked and unlit mast 1,893FT AMSL BRG 068 DEG MAG 2.8NM FM ARP, infringes conical SFC by 40FT.
- 4. Trees located parallel to RWY 07/25 CL, EXTD APRX 100M N, 100M S and along full length of RWY. Infringes transitional SFC by up to 4FT.

PHYSICAL CHARACTERISTICS

07/25 074 62a PCR 230/F/A/Y/T Sealed.

WID 30 RWS 90

AERODROME AND APPROACH LIGHTING

RWY 07/25 PAPI(1)

(1) Manually activated 2HR PN. PAPI intensity manually controlled by ARO via CTAF 126.5.

3.0 DEG52ET

118.95

OTHER LIGHTING

RWY 07/25: Night emergency lights AVBL 2HR PN.

ATS AND AERODROME COMMUNICATION FACILITIES

MELBOURNE CENTRE

LOCAL TRAFFIC REGULATIONS

1. RWY 07/25: all fixed wing ACFT must make MAX RAD turns at MNM speed at all RWY ends to avoid SFC damage.

2. Day VMC OPS only.

CTAF 126.5

FIA

CHARTS RELATED TO THE AERODROME

WAC 3352.

YTHN CERT