TYAGARAH

FULL NOTAM SERVICE NOT AVBL



NSW 283541S UTC +10 1533304E VAR 12 D

VAR 12 DEG E

UNCR

AD OPR Byron Shire Council, Works Depot, Bayshore Drive, Byron Bay, NSW, 2481. Email: council@byron.nsw.gov.au. PH 02 6685 9300. Website: www.byron.nsw.gov.au.

REMARKS

AD charges apply (pay station located NW of PRKG area).

Refer to website for current fees and charges.

AFRODROME OBSTACLES

The transitional slopes and APCH and TKOF areas on both sides of and at both ends of the RWY are infringed by trees.

PHYSICAL CHARACTERISTICS

05/23 31c Unrated. Grass and sand. RWY LEN 950M. WID 10

ATS AND AERODROME COMMUNICATION FACILITIES

FIA BRISBANE CENTRE 119.5 Circuit Area

CTAF 127.55

ADDITIONAL INFORMATION

- Gliding OPS HJ.
- Ultralights, Microlights, GA.
- Frequent Parachute OPS from FL140.
- RWY surface condition varies and is not consistent.
- RWY may be closed after rain.
- 6. Wildlife frequently OBS within RWS, pilots take precaution.
- Birds in VCY.
- Manned balloon ACT including launching and landing occur on private land ADJ to YTYH
 Airfield.
- Refer to website for detailed ALA INFO (type Tyagarah in search bar). All ACFT are REQ to make themselves familiar with YTYH Fly Neighbourly Procedure and, subject to OPR and Safety considerations, to comply with preferred circuit direction.

CHARTS RELATED TO THE AERODROME

WAC 3357.