

**WINDARLING****ELEV 1502****AVFAX CODE 6119**

WA

UTC +8

YWDG

300155S


1192314E

VAR 0 DEG E

CERT

AD OPR Yilgarn Iron Pty Ltd, 20 Walters Dr, Osborne Park, WA, 6017. Email:

windarling.aerodrome@mrl.com.au. ARO 0417 095 576, if not AVBL PH AD manager 0407 148 536.

**REMARKS**

1. Restricted OPS: PPR.
2. Night OPS not AVBL.

**APRONS AND TAXIWAYS**

TWY A: sealed, WID 15M.

**AERODROME OBSTACLES**

Vegetation:

- a. 3FT AGL PSN 50M north of RWY CL for the entire length of RWY 10/28 infringes transitional SFC.
- b. 8FT AGL BTN BRG 271 - 110 DEG MAG, 926M - 945M FM ARP.
- c. 8FT AGL BTN BRG 285 - 102 DEG MAG, 963M - 1,000M FM ARP.

**PHYSICAL CHARACTERISTICS**

10/28 103 61a Unrated. Sealed.

WID 30 RWS 90

**ATS AND AERODROME COMMUNICATION FACILITIES**

FIA MELBOURNE CENTRE

123.4 Circuit area.

**LOCAL TRAFFIC REGULATIONS**

1. From the TWY holding point, ACFT at THR RWY 28 may not be visible.
2. ACFT at THR RWY 10 and 28 may not be visible to each other.
3. ACFT ABV 5,700KG MTOW must turn at RWY ends only. MAX radius MNM speed turns.

**CTAF** 126.7**CHARTS RELATED TO THE AERODROME**

1. WAC 3351.
2. Also refer to AIP Departure and Approach Procedures.