
WILLIAMSON AVEAX CODE 4419

ELEV 104 FULL NOTAM SERVICE NOT AVBL



QLD UTC +10 YWIS
222824S 1501042E VAR 9 DEG E UNCR
AD OPR DCSO Rockhampton, 68 Western Street, Rockhampton, QLD,
4700. PH 07 4935 5000. Fax 07 4935 5024.

REMARKS

- 1. PPR.
- Contact range control on 07 4935 5000 prior to DEP to CFM FREQ RQMNTS.
- Caution: This aerodrome is not subject to routine serviceability inspection or NOTAM advice of unserviceabilities. Additional aerodrome data is available from the contact telephone numbers above or for MIL Aircrew: http://drnet.defence.gov.au/ARMY/ FORCOMD/Headquarters/AviationBranch/AvnAwDir/Pages/ OPAW.aspx

AERODROME OBSTACLES

High terrain 2.2NM N of AD.

METEOROLOGICAL INFORMATION PROVIDES

- METAR/SPECI.
- AWIS PH 07 3564 3747 Report faults to BoM.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA BRISBANE CENTRE 119.55 4000FT

LOCAL TRAFFIC REGULATIONS

- Inspection recommended at the end of each day's OPS to confirm if any functional damage to spray seal.
- MAX RAD turns at turning nodes.
- PRKG AVBL on main APN.

CTAF 126.7

ADDITIONAL INFORMATION

Kangaroo hazard exists, particularly around dawn and dusk.

CHARTS RELATED TO THE AERODROME

- WAC 3235.
- MIL Aerodrome Obstruction Chart Type A: NOV 2019.