Closed



Notification Report

Please be advised that the following ATS occurrence has been reported. Airservices encourages your feedback and any other information pertinent to this occurrence that you or your organisation is willing to share. This will facilitate the sharing of the lessons learned from the occurrence.

For additional information or to provide feedback on this occurrence, please contact s47E(d) @airservicesaustralia.com.

DISCLAIMER/TERMS OF RELEASE: Information provided in this report is copyright to Airservices and may not be reproduced or copied in any form or by any means or otherwise disclosed to any third party external to Air Services without the prior written consent of Airservices. Privacy of individual officers, organisations and/or operators is paramount, and where information identifying individual officers, organisations and/or operators is provided, it must remain secure and must not be released to third parties.

Report Number Occurrence Type Occurrence Date (UTC) Occurrence Time (UTC) Pilot Complaint/Report 20/09/2014 03:29 ATS-0131963 Reporting Group/Branch(SDL)/Unit: Occurrence Location Group/Branch(SDL)/Unit: Melbourne and Canberra TCU

Summary

UFO in CTA

Detailed Description

Melbourne and Canberra TCU

Pilot reported sighting a round object approx 45CM in diameter with something hanging below it at about A070

Airspace Category	Controlling	Authority	ATS Service Provided					
CTA	Airservices		Approach - surveillance					
	Cillo							
Location Code	Boaring (0	01 - 360)	Distance (nm)					
SANDR	(-) Y-		-					
	-63							
Latitude (dd:mm:ss)		(ddd:mm:ss)						
00:00:00 South	00:00:00	East						
.,50								
Principal Aircraft/G	round Vehicle							
Civil Australian Registered								
10,								
ACID/Callsion	Registration	ADEP	ADES					
s47F	s47F	YMHB	YMML					
60								
Other Aircraft/Gro	ound Vehicle							
ACID/Callsign	Registration	ADEP	ADES					
-	-	-	-					
Other Aircraft/Gro	ound Vehicle							





ACID/Callsign	Registration	ADEP	ADES
Occurrence Review			(
Accountable Leader s47F		Occurrence Review Due Da	ate
Responsible Group/Branch	n(SDL)/Unit		ate Armation Act 198
Does this occurrence requ Review? No	ire a detailed Occurrence		HOHMO
Accountable Leader may not closure of the record. The so service delivery. The Occurr understanding of contributor	ew is required for all 'Airservice minate an Occurrence Review cope and depth of analysis req ence Review must describe th y factors and assess the perfo nshots, Journal entries, etc.) s	officer/Delegate below, howevering the commensurate with the risk characteristics of the ocurrence of risk controls. All su	ever retains responsibility for ne potential risk to ATM ccurrence, demonstrate an
Occurrence Review Delega	ates	"ine	
Review Comments	ind'	3	
Personnel Involved (Note: Manager/s, etc.	Visibility is restricted) - Ente	er all personnel involved, e.	g. Controller/s, Shift
Was Fatigue a consideration	on in this occurrence?		
Was Fatigue a consideration - Review Completion			
Review Complete?			
Investigation			
Investigation Required?			
Investigator -			
Investigation Type			





Investigation considerations & other comments

Redeased by Airse vices Australia under the Free doministration Act. 1982.

Closed



Notification Report

Please be advised that the following ATS occurrence has been reported. Airservices encourages your feedback and any other information pertinent to this occurrence that you or your organisation is willing to share. This will facilitate the sharing of the lessons learned from the occurrence.

For additional information or to provide feedback on this occurrence, please contact \$47E(d) @airservicesaustralia.com.

DISCLAIMER/TERMS OF RELEASE: Information provided in this report is copyright to Airservices and may not be reproduced or copied in any form or by any means or otherwise disclosed to any third party external to Airservices without the prior written consent of Airservices. Privacy of individual officers, organisations and/or operators is paramount, and where information identifying individual officers, organisations and/or operators is provided, it must remain secure and must not be released to third parties.

Report Number Occurrence Type Occurrence Date (UTC) Occurrence Time (UTC)

ATS-0130233 Other - Safety Related 05/07/2014 13:30

Reporting Group/Branch(SDL)/Unit: Occurrence Location Group/Branch(SDL)/Unit:

BN TCU 1 BN TCU

Summary

Possible UFO sighted at Suncorp Stadium

Detailed Description

Pilot of **s47F** after landing AF called with the following information.

s47F tracking from Royal Brisbane Hospital to Archerfield, when at about A015, was advised by crewman that there was possibly a flying object in the area of Suncorp Stadium at about A006. Aircraft turned to investigate, but nothing was seen by pilot (under NVG). Crewman thought it was an UAV.

Nothing was painted on the TMA radar.

The area was on the border of Contro Zone and class G airspace

Airspace Category Controlling Authority ATS Service Provided

CTA Airservices Approach - surveillance

Location Code Bearing (001 - 360) Distance (nm)

YRBH 210 1.6

Latitude (dd:mm:ss) Longitude (ddd:mm:ss)

00:00:00 South 0000:00:00 East

----- Principal Aircraft/Ground Vehicle -----

ವ√il Australian Registered

ACID/Callsign Registration ADEP ADES \$47F YRBH YBAF

----- Other Aircraft/Ground Vehicle ------

RPAS (UAV) / Model Aircraft

Closed



ACID/Callsign	Registration	ADEP	ADES	
Other Aircraft/G	round Vehicle			
				000
ACID/Callsign	Registration	ADEP	ADES	100
-	-	-	-	
Occurrence Review			10/1	
Accountable Leader s47F		Occurrence Review Due	Date	
Responsible Group/Bran	ch(SDL)/Unit	Ś	110,	
Does this occurrence red Review?	uire a detailed Occurrence	Occurrence Review Due		
No		616		
Accountable Leader may na closure of the record. The service delivery. The Occu understanding of contribute	view is required for all 'Airservion in attention and occurrence Reviescope and depth of analysis represented Review must describe for factors and assess the perfensions, Journal entries, etc.)	w Onicer/Delegate below, he quired is commensurate with a risk characteristics of the formance of risk controls. All	owever retains responsi th the potential risk to AT occurrence, demonstra	ΓM ΄ ate an
Occurrence Review Deleg	gates			
	Misc			
Review Comments	S			
	;(0)			
Personnel Involved (Note Manager/s, etc.	visibility is restricted) - En	ter all personnel involved,	e.g. Controller/s, Shift	t
Was Estimus salasidare	tion in this converges?			
Was Fatigue a considerar	uon in this occurrence?			
7				

Initial Review - Other

Review Complete?

Delegate ReviewerReview Date\$47F06/07/2014





Freedom of Information Advantage of the Property of the Proper

Comments

OI may be interested. Iw ill pass it on to them. Closed CIRRIS RS, \$47F 6/7/14

Review Completion

Close Occurrence

Investigation

Investigation Required?

Investigator

Investigation Type

Investigation considerations & other comments

Occurrence Close

es Australia IIII **Close Off Date**

Closing Comments

Close this Record?

Review - Other (Historical)

Responsible Supervisor **Review Date** s47F

06/07/2014

Comments

OI may be interested. Iw ill pass it on to them. Closed CIRRIS RS, s47F 6/7/14

Review Completion

Close Occurrence

Investigation Commencement Criteria

<Undefined>

If Other, Please Specify



Assigned IRM

Redeased by Airsenices Australia under the Freedom of Information Act. 1982